



## PRO-FORMA INVOICE

Co Reg No : 199405410K

**THIS IS NOT AN OFFICIAL TAX INVOICE**

GST Reg No : MR-8500111-X

| Invoice Name & Address                                                                                                                                              | Owner Name & Vehicle Info |                                      |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------|--------------------------------------|
| AIG Asia Pacific Insurance Pte.<br>Ltd.<br>MOTOR CLAIM DEPARTMENT<br>78 SHENTON WAY #09-16<br>AIG BUILDING<br>SINGAPORE 079120<br>Contact No 64191000<br>03/08/2021 | Cust No/Name              | LCV11148/MEE SOOK HONG CIUPA         |
|                                                                                                                                                                     | Reg No/Reg Date           | SJW6663H / 18/09/2019                |
|                                                                                                                                                                     | Date In/Mileage           | 02/08/2021/ 21071                    |
|                                                                                                                                                                     | Chassis/Package           | KNAF5416MK5052935 /KC17P             |
|                                                                                                                                                                     | Engine No                 | G4FGKH749527                         |
|                                                                                                                                                                     | Make/Model                | KIA/CERATO 1.6 A GT LINE H171        |
|                                                                                                                                                                     | Colour/Trim               | SWP SNOW WHITE PEAR/ WK SATURN BLACK |

| Account No                      | Terms    | Date/Time Printed                                                                                                                                   | CSE | Operator     | WIP No |            |       |        |         |
|---------------------------------|----------|-----------------------------------------------------------------------------------------------------------------------------------------------------|-----|--------------|--------|------------|-------|--------|---------|
| LAX00000                        | Credit   | 06/10/2021/ 10:46                                                                                                                                   | BLK | 260 / AiTing | 37209  |            |       |        |         |
| Description of Goods / Services |          |                                                                                                                                                     |     |              | Qty    | Unit Price | Disc% | Amount |         |
| E                               | PNT88000 | REPLACE DAMAGED PARTS, REPLACE ROOF PANEL, LH FRONT OUTER PILLAR, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME |     |              |        |            | ✓     |        | 2400.00 |
| E                               | PNT98000 | RESPRAY ON ROOF PANEL, LH FRONT OUTER PILLAR, AND ALL OTHER AFFECTED AREAS TO THE SAME                                                              |     |              |        |            | ✓     |        | 700.00  |
| E                               | PNT88000 | REPLACE FRONT WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST                                                                                          |     |              |        |            | ✓     |        | 240.00  |
| M                               | SUNDRY   | APPLY FRONT WINDSCREEN GLASS SEALANT                                                                                                                |     |              |        |            | ✓     |        | 80.00   |
| E                               | PNT88000 | REMOVE & INSTALL REAR WINDSCREEN GLASS TO FACILITATE REPAIR                                                                                         |     |              |        |            | ✓     |        | 240.00  |
| M                               | SUNDRY   | APPLY REAR WINDSCREEN GLASS SEALANT                                                                                                                 |     |              |        |            | ✓     |        | 80.00   |
| A                               | 52900099 | REMOVE & INSTALL DASHBOARD TO FACILITATE REPAIR                                                                                                     |     |              |        |            | ✓     |        | 400.00  |
| E                               | PNT88000 | REMOVE & INSTALL LH FRONT & LH REAR DOOR TO FACILITATE REPAIR                                                                                       |     |              |        |            | ✓     |        | 200.00  |
| E                               | PNT88000 | CLEAN & VACUUM FRONT SHATTERED GLASS DEBRIS                                                                                                         |     |              |        |            | ✓     |        | 80.00   |
| E                               | PNT88000 | REMOVE & INSTALL ALL PILLAR TRIMS TO FACILITATE REPAIR                                                                                              |     |              |        |            | ✓     |        | 80.00   |
| A                               | 54900099 | CHECK WIRING & CHASSIS ELECTRICAL SYSTEM                                                                                                            |     |              |        |            | ✓     |        | 30.00   |
| A                               | 10028901 | CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE                                                                              |     |              |        |            | ✓     |        | 120.00  |
| M                               | SUNDRY   | APPLY BODY SEALANT ON AFFECTED AREAS                                                                                                                |     |              |        |            | ✓     |        | 80.00   |
| M                               | SUNDRY   | PERFORM RUST PREVENTION ON AFFECTED AREAS                                                                                                           |     |              |        |            | ✓     |        | 40.00   |
| M                               | SUNDRY   | SUNDRIES                                                                                                                                            |     |              |        |            | ✓     |        | 20.00   |



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**  
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

**THIS IS NOT AN OFFICIAL TAX INVOICE**

GST Reg No : MR-8500111-X

| Invoice Name & Address                                                                                                                                                  | Owner Name & Vehicle Info |                                      |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------|--------------------------------------|
| AIG Asia Pacific Insurance Pte.<br>Ltd.<br>MOTOR CLAIM DEPARTMENT<br>78 SHENTON WAY #09-16<br>AIG BUILDING<br>SINGAPORE 079120<br>Contact No 64191000<br><br>03/08/2021 | Cust No/Name              | LCV11148/MEE SOOK HONG CIUPA         |
|                                                                                                                                                                         | Reg No/Reg Date           | SJW6663H / 18/09/2019                |
|                                                                                                                                                                         | Date In/Mileage           | 02/08/2021/ 21071                    |
|                                                                                                                                                                         | Chassis/Package           | KNAF5416MK5052935 /KC17P             |
|                                                                                                                                                                         | Engine No                 | G4FGKH749527                         |
|                                                                                                                                                                         | Make/Model                | KIA/CERATO 1.6 A GT LINE H171        |
|                                                                                                                                                                         | Colour/Trim               | SWP SNOW WHITE PEAR/ WK SATURN BLACK |

| Account No                      | Terms  | Date/Time Printed                                             | CSE | Operator     | WIP No |            |       |         |
|---------------------------------|--------|---------------------------------------------------------------|-----|--------------|--------|------------|-------|---------|
| LAX00000                        | Credit | 06/10/2021/ 10:46                                             | BLK | 260 / AiTing | 37209  |            |       |         |
| Description of Goods / Services |        |                                                               |     |              | Qty    | Unit Price | Disc% | Amount  |
| A 52900099                      |        | REMOVE & INSTALL ROOF GLASS TO FACILITATE REPAIR              |     |              |        |            |       | 300.00  |
| A 52900099                      |        | REPLACE ROOF LINING                                           |     |              |        |            |       | 400.00  |
| A 52900099                      |        | REMOVE & INSTALL FRONT SEATS AND CARPETS TO FACILITATE REPAIR |     |              |        |            |       | 200.00  |
| A 52900099                      |        | REMOVE & INSTALL REAR SEATS AND CARPETS TO FACILITATE REPAIR  |     |              |        |            |       | 200.00  |
| A 52900099                      |        | REMOVE & INSTALL LH B PILLAR TO FACILITATE REPAIR             |     |              |        |            |       | 120.00  |
| S SPECIALISTJOB                 |        | SUPPLY & INSTALL FRONT WINDSCREEN GLASS SOLAR FILM - RIKECOOL |     |              |        |            |       | 220.00  |
| S SPECIALISTJOB                 |        | SUPPLY AND INSTALL SUN ROOF SOLAR FILM - RIKECOOL             |     |              |        |            |       | 120.00  |
| X EXC                           |        | INSURANCE EXCESS                                              |     |              |        |            |       | -600.00 |
| X                               |        | PANEL ASSY-PILLAR OUTER,LH                                    |     |              | 1.00   | 2345.00    | 20.00 | 1876.00 |
| X                               |        | PANEL-ROOF                                                    |     |              | 1.00   | 843.00     | 20.00 | 674.40  |
| X                               |        | HEADLINING ASSY                                               |     |              | 1.00   | 1584.00    | 20.00 | 1267.20 |
| X                               |        | MOULDING ASSY-ROOF,LH                                         |     |              | 1.00   | 43.00      | 20.00 | 34.40   |
| X                               |        | MOULDING-WINDSHIELD GLASS                                     |     |              | 1.00   | 56.00      | 20.00 | 44.80   |
| X                               |        | GLASS-WINDSHIELD                                              |     |              | 1.00   | 821.00     | 20.00 | 656.80  |
| X                               |        | W/STRIP ASSY-FR DR SIDE LH                                    |     |              | 1.00   | 102.00     | 20.00 | 81.60   |
| X                               |        | STOPPER-GLASS                                                 |     |              | 2.00   | 4.00       | 20.00 | 6.40    |
| X                               |        | PAD-WINDSHIELD GLASS                                          |     |              | 20.00  | 2.00       | 20.00 | 32.00   |
| Z TEXT                          |        | AIG OD CLAIM                                                  |     |              |        |            |       |         |
|                                 |        | DOA : 01.08.21                                                |     |              |        |            |       |         |
|                                 |        | SURVEYOR STEVE-LKK 03.08.21                                   |     |              |        |            |       |         |
|                                 |        | POLICY NO : 1900161517                                        |     |              |        |            |       |         |
|                                 |        | REPAIR 14 DAYS                                                |     |              |        |            |       |         |

Guarantee Your Warranty, Maintain with Cycle & Carriage!

|                 |           |               |           |
|-----------------|-----------|---------------|-----------|
| Parts           | 4,673.60  | Nett          | 10,423.60 |
| Labour          | 5,710.00  | 7% GST on     | 729.65    |
| Standard Menu   | 0.00      |               |           |
| Specialist Job  | 340.00    | Total Payable | 11,153.25 |
| Diagnostics Job | 0.00      |               |           |
| Sundry/Others   | -300.00   |               |           |
| Total(w/o GST)  | 10,423.60 |               |           |

This is not an official tax invoice.  
 This is a computer generated document, no signature is required.



## Exceptional Journeys

INSURANCE CO. : **AIG**

Supplementary Parts For Registration No.: **SJW 6663 H**

|   | <b><u>Materials</u></b>     | <b><u>Cost (\$)</u></b> |       |
|---|-----------------------------|-------------------------|-------|
| 1 | W/strip assy-Fr dr side LH  | 102.00                  | ✓ CVT |
| 2 | Stopper-glass (x2)          | 8.00                    | ✓ nec |
| 3 | Pad-windshield glass (x20)  | 40.00                   | ✓ nec |
|   | <b>Total Materials</b>      | <b>150.00</b>           |       |
|   | <b>Less 20% discount</b>    | <b>30.00</b>            |       |
|   | <b>Total after discount</b> | <b>120.00</b>           |       |

|   | <b><u>Labour</u></b>                            | <b><u>Cost (\$)</u></b> |   |
|---|-------------------------------------------------|-------------------------|---|
| 1 | Supply & install sun roof solar film - Rikecool | 120.00                  | ✓ |
|   | <b>Total labour</b>                             | <b>120.00</b>           |   |
|   | <b>Total amount</b>                             | <b>240.00</b>           |   |
|   | <b>7% GST</b>                                   | <b>16.80</b>            |   |
|   | <b>Grand total</b>                              | <b><u>\$ 256.80</u></b> |   |

Thank You.  
Yours faithfully

LOI AI TING  
SENIOR OFFICER - ADMIN  
**KIA SERVICE CENTRE**  
DID : 6568 4556 / 6568 4501  
FAX : 6567 5258 / 6565 1240

CAR NO: SJW 666314WIP: 37209 (ADDITIONAL PARTS CHANGE)

| S/NO | PARTS NAME                            | ? / SUPP | CSA SIGN | PHOTO TAKEN | REMARKS          |
|------|---------------------------------------|----------|----------|-------------|------------------|
| 1    | W/strip Front Door                    | ? / SUPP |          | ✓ TN        | Start<br>31/8/21 |
| 2    | Strip Front Windshield                | ? / SUPP |          | ✓ NS        |                  |
| 3    | Spacer Front & Rear Windshield (Rear) | ? / SUPP |          | ✓ NS        |                  |
| 4    |                                       | ? / SUPP |          |             |                  |
| 5    |                                       | ? / SUPP |          |             |                  |
| 6    |                                       | ? / SUPP |          |             |                  |
| 7    |                                       | ? / SUPP |          |             |                  |
| 8    |                                       | ? / SUPP |          |             |                  |
| 9    |                                       | ? / SUPP |          |             |                  |
| 10   |                                       | ? / SUPP |          |             |                  |
| 11   |                                       | ? / SUPP |          |             |                  |
| 12   |                                       | ? / SUPP |          |             |                  |
| 13   |                                       | ? / SUPP |          |             |                  |
| 14   |                                       | ? / SUPP |          |             |                  |
| 15   |                                       | ? / SUPP |          |             |                  |
| 16   |                                       | ? / SUPP |          |             |                  |
| 17   |                                       | ? / SUPP |          |             |                  |
| 18   |                                       | ? / SUPP |          |             |                  |
| 19   |                                       | ? / SUPP |          |             |                  |
| 20   |                                       | ? / SUPP |          |             |                  |

|                                   | DATE | TAKEN BY |
|-----------------------------------|------|----------|
| PHOTO BEFORE PAINT                |      |          |
| PHOTO AFTER PAINT                 |      |          |
| PHOTO OF MOUNT TO CELLULETE BENCH |      |          |
| REMOVE AND INSTALL ENGINE         |      |          |
| REMOVE AND INSTALL DASHBOARD      |      |          |
| REMOVE & INSTALL FUEL TANK        |      |          |
| PHOTO UNDERCARRIAGE PARTS         |      |          |

MODEL: Ceato 1.6SURVEYOR: Lkk-Steve

 **Fault Code Searching**

Rescan

Clear All DTC

Clear DTC

Save



12/12

| System | Status         | Result |
|--------|----------------|--------|
| ENGINE | No Current DTC | Good   |
| AT     | No Current DTC | Good   |
| ABSESC | No Current DTC | Good   |
| AIRBAG | No Current DTC | Good   |
| AIRCON | No Current DTC | Good   |
| EPS    | No Current DTC | Good   |

| System | DTC | Description | State |
|--------|-----|-------------|-------|
|--------|-----|-------------|-------|

No History or Pending DTC

S/W Ver. M-E-K-01-00-0253

VCI Ver. 02.59

ECU Ver. M-E-K-01-00-0193

OS Ver. Android 10