

REF:

ASSIGNMENT

Veh No: 3DJ88/0B. Yr Reqn: 2016 / Oct.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz E220D c.c 1950

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading 48847 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDD2130042 A 057800

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275/35R19

R: 275/35R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

Front

Rear

R/Bal. 06 mm

L/Bal. 06 mm

D.O.A.

*Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
-------------	----------------------

TP A16.

$mv :$

	PV :
--	------

Nett:

☐: Prelim. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: : Site Insp (\$

: Interview (\$

Transportation:

Photos

Others