

TOTAL

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

HP
Date: 02.08.2021
Time: 09:54:09
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305480940
REGN NO : SHC1832Z
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 28.04.2016
DATE/TIME IN : 30.07.2021 23:30
ACCIDENT DATE : 30.07.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0594-G MIRROR ASSY-RR VIEW O/S R 1 670.00 20.00 536.00 *br*

SUB-TOTAL : 536.00

JOB NATURE

0000 PB PANEL BEATING

~~100.00~~ *50*

0001 SP SPRAYPAINT CHARGE

~~100.00~~ *50*

SUB-TOTAL : 200.00

TOTAL : 736.00

Humam
MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Res
Hp 90010068
1 days
4/5
02/08/21 @ 1520
Resurvey after repair

DELGRO**ComfortDelGro Engineering Pte Ltd**

205 Braddell Road Singapore 579701

Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

205 Braddell Road Singapore 579701

59 Loyang Drive Singapore 508969

383 Sin Ming Drive Singapore 575717

Date/Time: 02.08.2021 09:55

Page : 1

ARC Repair TP(CLS0)1

JOB CARD

Sales Order: 4104165

JC NO.: 305480940

COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755 (O)

REGN NO.: SHC1832Z	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL I-40	DATE/TIME IN 30.07.2021 23:30
YR OF MANU 28.04.2016	TARGET DATE
CHASSIS CODE KMHLB41UMGU087887	COMPLETION DATE/TIME:


UNT CARD NO.

JOB DESCRIPTION

Accident Date: 30.07.2021
NATURE: 3P 30.07.2021

S/NO	LABOR CODE
000020	PB
000030	SP

DESCRIPTION
PANEL BEATING
SPRAYPAINT CHARGE



WORKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Ledgement Slip

Exit Pass

No.: **SHC1832Z** **JU NTUC LKK**Vehicle No.: **SHC1832Z**

f Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Please report correctly the details of the accident to speed up the claims process.

This Form must be completed by the Policyholder and/or the Authorised Driver.

Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	31/07/2021 16:42 (SGT)
Date of Accident	30/07/2021 22:50 (SGT)
Exact Location of Accident	Thomson Rd, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC1832Z
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Company Reg No	1XXXXX821R
Email Address	fleetsafety@cdgtaxi.com.sg
Mobile Phone No	(Phone) +65-96167384
Alternative Phone No	(Office) +65-65508768

VEHICLE PARTICULARS

Manufacturer	Hyundai
Model	I40
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1685

INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Type of Coverage	ThirdPartyFireTheft
Fleet Policy	Yes
Policy Number	VFX/P2419138
Cover Note Number	-

DRIVER

Name of Driver	NARINDAR SINGH JASWAL
NRIC No	XXXXX618G



Accident report SJ04217V000C

Date of Birth	18/06/1958
Location	Outdoor
Date of Driving Pass.	17/06/1986
Driving experience	35 YEARS AND 1 MONTH
Gender	Male
Mobile Number	(Phone) +65-96167384
Alt. Phone Number	-
Email Address	fleetsafety@cdgtaxi.com.sg
Address	BLK 140 BUKIT BATOK STREET 11 #09-41
Address complement	-
Postcode	650140
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

ON 300721 AT AROUND 2250HRS, I WAS DRIVING MY VEHICLE A SHC1832Z ALONG THOMSON ROAD ON THE EXTREME LEFT LANE. I WAS STATIONARY AS THERE WAS A VEHICLE IN FRONT OF ME ALSO STATIONARY. SUDDENLY VEHICLE B SHD1293Z SIDESWIPE ME AT A FAST SPEED AND HIT MY RIGHT SIDE MIRROR DISLODGING IT. THERE WAS DAMAGES TO MY RIGHT SIDE MIRROR. THERE WAS NO INJURIES

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	FILE IS NOT SUITABLE
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD1293Z
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	PANG HEE KIAT

No
ct Number
ess
ress complement
stcode
surance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

SXXXX674Z
(Phone) +65-90691515

-
-
-
-
-
-
-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time 31/11/21 0020

Witnessed by Reporting Centre Personnel KHAI RUL

Sketch Plan



Describe Circumstances of the Accident

ON 300721 AT AROUND 2250HRS, I WAS DRIVING MY VEHICLE A SHC1832Z ALONG THOMSON ROAD ON THE EXTREME LEFT LANE. I WAS STATIONARY AS THERE WAS A VEHICLE IN FRONT OF ME ALSO STATIONARY. SUDDENLY VEHICLE B SHD1293Z SIDESWIPE ME AT A FAST SPEED AND HIT MY RIGHT SIDE MIRROR DISLODGING IT. THERE WAS DAMAGES TO MY RIGHT SIDE MIRROR. THERE WAS NO INJURIES

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time 31/9/21 06 20

Witnessed by Reporting Centre Personnel KHANBUL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	821R
Vehicle No.:	SHC1832Z
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Aug 2021
Vehicle Make:	HYUNDAI
Vehicle Model:	I40 1.7 CRDI F/L AT ABS AIRBAG 4DR
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	D4FDGU614049
Chassis No.:	KMHLB41UMGU087887
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$20,239.00
Original Registration Date:	28 Apr 2016
First Registration Date:	28 Apr 2016
Transfer Count:	0
Actual ARF Paid:	\$20,335.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Apr 2024
PARF Rebate Amount:	\$14,234.00
COE Expiry Date:	27 Apr 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$36,862.00
COE Rebate Amount:	\$12,607.00
Total Rebate Amount:	\$26,841.00
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 02 Aug 2021

OK