



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:STACEY NG			Ref: CC4/ASM21008178/Aps3q2 Date: 15/12/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLQ 9141K	Veh. Inspected	SMG 2306P	
Policy No.	GA546746	Coverage (\$)	0.00	
Claim No.	S1M03EWO	Excess (\$)	0.00	
Assign From		Assign Date	03/08/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA FIT	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	GP51331052	Colour	BLUE	
Odometer	72749 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R15	MAXXIS	6 mm	
L/H Front Tyre	195/60 R15	MAXXIS	6 mm	
R/H Rear Tyre	195/60 R15	MAXXIS	6 mm	
L/H Rear Tyre	195/60 R15	MAXXIS	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/08/2021	Inspection Date	04/08/2021	
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	