

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422 / 6745 4422 Fax : 6747- 6720 REG NO 200501102H

MSIG INSURANCE (S) PTE LTD

4 Shenton Way # 21 - 01

SGX Centre 2

Singapore 068807

Hot line : 6827 - 7660

Fax : 6225- 7402 (CLAIM)

Quotation

DATE : 10.08.2021

VEH NO : SLR1351T

MODEL : Opel Astra

D O A : 02.08.2021

YR REF : SLF390A

Attn : Motor Claim Dept

(pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SLR1351T (OPEL ASTRA)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Bumper <i>Distorted</i>	1	1,740.00 ✓
2	Rear Bumper Side Holder - LH & RH <i>new</i>	2	114.00 ✓
3	Rear Bumper Reflector - RH <i>new</i>	1	65.00 ✓
4	Rear Bumper Reinforcement <i>2478</i>	1	710.00 ✓
5	Tail Lamp - RH <i>Cracked</i>	1	738.00 ✓
			\$ 3,367.00
	Less 10%		(336.70)
			\$ 3,030.30

S/NET ITEMS

1	Rear Bumper Clips <i>new</i>	1 set	\$ 50.00 ✓
2	Reverse Sensor <i>Damaged</i>	1	\$ 195.00 ✓
			\$ 245.00
	Total parts		
			\$ 3,275.30

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$ 400.00 <i>200</i>
2	To putty and spray up paint works	\$ 500.00 <i>200</i>
3	To check wiring	\$ 50.00 <i>30</i>
4	To remove reverse sensor	\$ 100.00 <i>50</i>
		\$ 1,050.00

RE : ESTIMATE FOR ACCIDENT REPAIR SLR1351T (OPEL ASTRA)

GRAND TOTAL

\$ 4,325.30

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 2955.20
CP/P)
030 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: