

Estimation

Date
Vehicle
Make/Model
Chassis No.

GBG 5855 G
TOYOTA HIACE
JTFHT02P800233295

No.	Description	Unit	Unit Price	Amount
	Parts Replacment			
1	TAILGATE	1	\$ 1,969.00	\$ <i>bf</i> 1,969.00
2	TAILGATE HANDLE GARNISH	1	\$ 155.00	\$ <i>X</i> 155.00
3	TAILGATE LOGO - TOYOTA	1	\$ 75.00	\$ <i>new</i> 75.00
4	TAILGATE STICKER - TOYOTA	1	\$ 40.00	\$ <i>new</i> 40.00
5	TAILGATE STICKER - HIACE	1	\$ 47.00	\$ <i>new</i> 47.00
6	TAILGATE LOCK	1	\$ 275.00	\$ <i>X</i> 275.00
7	TAILGATE LOCK COVER	1	\$ 52.00	\$ <i>X</i> 52.00
8	TAILGATE LOCK CATCH	1	\$ 62.00	\$ <i>X</i> 62.00
9	TAILGATE INNER BOARD	1	\$ 408.00	\$ <i>new</i> 408.00
10	TAILGATE HINGE L+R	2	\$ 76.00	\$ <i>X</i> 152.00
11	TAILGATE DAMPER L+R	2	\$ 355.00	\$ <i>X</i> 710.00
12	TAILGATE STOPPER L+R	2	\$ 25.00	\$ <i>X</i> 50.00
13	TAILGATE WEATHERSTRIP	1	\$ 395.00	\$ <i>new</i> 395.00
14	TAIL LAMP L+R <i>LH X</i>	2	\$ 300.00	\$ <i>RH new</i> 600.00
15	TAIL LAMP PANEL RH	1		\$ <i>RR</i> -
16	REAR BUMPER	1	\$ 400.00	\$ <i>de</i> 400.00
17	REAR BUMPER RETAINER L+R <i>LH X</i>	2	\$ 29.00	\$ <i>RH de</i> 58.00
18	REAR SIDE BUMPER RH	1	\$ 100.00	\$ <i>de</i> 100.00
19	REAR SIDE BUMPER RETAINER RH	1	\$ 30.00	\$ <i>X</i> 30.00
20	REAR FENDER RH	1		\$ <i>X</i> -
21	REAR FENDER COWLING RH	1		\$ <i>X</i> -
22	END PANEL	1	\$ 387.00	\$ <i>bf</i> 387.00
23	END PANEL INNER PANEL	1	\$ 1,155.00	\$ <i>Ry</i> 1,155.00
24	END PANEL TOP GARNISH	1	\$ 269.00	\$ <i>bf</i> 269.00
25	REAR QUARTER PANEL RH	1	\$ 374.00	\$ <i>X</i> 374.00
26	FLOOR PANEL	1	\$ 2,879.00	\$ <i>Ry</i> 2,879.00
27	EXHAUST PIPE	1	\$ 591.00	\$ <i>?</i> 591.00
28	EXHAUST MOUNTING SET	2	\$ 59.00	\$ <i>?</i> 118.00
29	EXHAUST HEAT SHIELD	1	\$ 91.00	\$ <i>X</i> 91.00
30	SPARE TYRE BRACKET	1	\$ 295.00	\$ <i>X</i> 295.00
			Total	\$ 11,737.00
			Less 25%	\$ 2,934.25
			Total	\$ 8,802.75

	S/Nett Items			
1	TAILGATE WINDSCREEN SEALANT	1	150	\$ <i>60</i> 150.00

2	TAILGATE HANDLE GARNISH CLIPS	1	100	\$ X	100.00
3	TAILGATE STICKER - 70KM/H	1	80	\$ 30	80.00
4	TAILGATE INNER BOARD CLIPS	1	100	\$ 30	100.00
5	REAR NUMBER PLATE	1	200	\$ X	200.00
6	TAIL LAMP CLIPS	1	50	\$ 20	50.00
7	TAIL LAMP PANEL SEALANT	1	80	\$ X	80.00
8	REAR BUMPER CLIPS	1	100	\$ 30m	100.00
9	REAR BUMPER REVERSE SENSOR SET	1	300	\$ 200m	300.00
10	REAR FENDER SEALANT	1	200	\$ X	200.00
11	REAR FENDER COWLING	1	100	\$ X	100.00
12	END PANEL SEALANT	1	200	\$ 40	200.00
13	END PANEL INNER PANEL SEALANT	1	200	\$ X	200.00
14	REAR QUARTER PANEL SEALANT	2	120	\$ X	240.00
15	FLOOR PANEL SEALANT	1	300	\$ X	300.00
16	FLOOR PANEL TOP BOARD	1	4000	\$ 500	4,000.00
			Total	\$	6,400.00

	LABOUR				
1	PANEL BEATING ON AFFECTED AREAS	1	2400	\$ 700	2,400.00
2	SPRAY PAINT ON AFFECTED AREAS	1	1600	\$ 800	1,600.00
3	TO RNR REAR WINDSCREEN	1	400	\$ 120	400.00
3	TO RNR REAR EXHAUST	1	250	\$ 60	250.00
4	TO CHECK WIRING AND TAILLAMP FUNCTION	1	150	\$ 30	150.00
5	TO RNR REAR TRIMS AND UPHOISTERY	1	400	\$ 60	400.00
6	TO CHECK WATER LEAK	1	150	\$ 20	150.00
7	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	1	600	\$ X	600.00
8	TO RNR REAR TAILGATE MECHANISM	1	400	\$ 60	400.00
9	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	1	150	\$ 30	150.00
10	TO PERFORM RUST PROOFING	1	600	\$ 30	600.00
			Total	\$	7,100.00

Parts Replacement Amount	\$	15,202.75
Total Amount For Labour	\$	7,100.00
Total Amount	\$	22,302.75

Tanpin 97495749
 'wp' 5/8/21 @ 1040
 c/s Resurvey after repair
 Tanpin @ Mauto.com
 7 days.

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	787K
Vehicle Details	
Vehicle No.:	GBG5855G
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Aug 2021
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE VAN TURBO 5DR MT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	1KD2750128
Chassis No.:	JTFHT02P800233295
Maximum Power Output:	-
Open Market Value:	\$28,138.00
Original Registration Date:	08 Sep 2017
First Registration Date:	08 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$1,407.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	07 Sep 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$31,040.00
COE Rebate Amount:	\$18,684.00
Total Rebate Amount:	\$18,684.00

The information contained herein is correct as at 02 Aug 2021

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	02/08/2021 18:30 (SGT)
Date of Accident	30/07/2021 15:54 (SGT)
Exact Location of Accident	Tampines Ave 1, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBG5855G
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	PAOLINI BUILDING MATERIALS PTE LTD
Company Reg No	2XXXXX787K
Email Address	KENTWONG432@YAHOO.COM.SG
Mobile Phone No	(Phone) +65-96125740
Alternative Phone No	(Home) +65-96125740

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Hiace
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Auto
CC	0

INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5118708469
Cover Note Number	-

DRIVER

Name of Driver	WONG WAI KEAT
Passport No/FIN	GXXXX309W

Date Of Birth	15/09/1987
Occupation	Outdoor
Date Of Driving Pass	20/12/2016
Driving experience	4 YEARS AND 7 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96125740
Alt. Phone Number	-
Email Address	KENTWONG432@YAHOO.COM.SG
Address	5 PEREIRA ROAD #07-02
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHED

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	WITH OWNER
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKU3449D
Vehicle Manufacturer	Honda
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	KWEK EN HONG
NRIC No	SXXXX956B
Contact Number	-

Address	-
Address complement	-
Postcode	-
Insurance Company Name	Auto & General Insurance (Singapore) Pte. Limited.
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	WONG WAI KEAT
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	GBG5855G
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
 (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 (ii) investigating the accident and/or my claims;
 (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


PAOLINI BUILDING MATERIALS PTE LTD

PAOLINI BUILDING MATERIALS PTE LTD

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Describe Circumstances of the Accident

On 30-07-2021 at about 1545hrs, I was travelling along Tampines Ave 1 Towards Tampines Avenue 8. While heading straight all of a sudden I felt an impact from my rear. then I noticed a vehicle SKU 3449D had collided into my rear.

Declaration

(We declare the foregoing particulars are true in every respect.)

PAOLINI BUILDING MATERIALS PTE LTD

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel