



Claim	S1M03EV6
Reference	CS3/ASM21008211/Gqce2 
Loss Date	31 July 2021
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	3 Aug 2021 9:36:48 AM
Request Date	3 August 2021
Due Date	
Services	Pending verification - Direct Settlement

Actions

Next Step

Wait for: Approve
invoice

Add Invoice

Vehicle Information

Incident	GBF5367D
Vehicle	
Registration #	
Make	TPVD Toyota
Model	Dyna

Service Address

’ ’ ’

Primary Contact/Insured

P.I.L. CONSORTIUM PTE LTD

2 SIMS CLOSE, #02-07 GEMINI @ SIMS, 387298,

Singapore

67434424



Claim Handler

CHAN Kian Chuan
68805444
kianchuan.chan@axa.com.sg

Additional Instructions

Messages1 Invoices History Documents Assessment Metrics Notes

Document Type

Document SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2105626.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	11 August 2021
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	11 August 2021

FAQ English (SG) ▼ Elaine Kuan ▼			E	SUBTYPE	AUTHOR	DATE UPLOADED
	Service Requests	...	dence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	11 August 2021
	 AXA Immediate Advice - GBF5367D (PRS).pdf.pdf		Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	5 August 2021
	 EMAIL FROM WS.msg.msg		Letters and Correspondence	Others	NIKAM Santosh Pandurang	4 August 2021
	 GIA TP.pdf.pdf		Reports & Statement	GIA Report	VISHNU BATHAM Shekhar	3 August 2021
	 WS.pdf.pdf		Letters and Correspondence	Workshop	VISHNU BATHAM Shekhar	3 August 2021
	 EMAIL TP REG.pdf.pdf		Letters and Correspondence	Workshop	VISHNU BATHAM Shekhar	3 August 2021