

|   |        |      |             |
|---|--------|------|-------------|
| 1 | of 2 ? | 100% | Find   Next |
|---|--------|------|-------------|



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

|                                                                       |                                            |                 |                                  |  |
|-----------------------------------------------------------------------|--------------------------------------------|-----------------|----------------------------------|--|
| Affiliated to Federation Internationale Des Experts En Automobile     |                                            |                 |                                  |  |
| SOMPO INSURANCE SINGAPORE PL                                          |                                            |                 | Ref: CS/SMO21008214/18 Kqf3      |  |
| 50 RAFFLES PLACE #03-03                                               |                                            |                 | Date: 04/08/2021                 |  |
| SINGAPORE LAND TOWERSINGAPORE 048623                                  |                                            |                 | Code: SMO                        |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                     |                                            |                 |                                  |  |
| Insured Veh.                                                          | SGS 19P                                    | Veh. Inspected  | SMT 7377H                        |  |
| Policy No.                                                            |                                            | Coverage (\$)   | 0.00                             |  |
| Claim No.                                                             | CMTD2102301/RUC                            | Excess (\$)     | 0.00                             |  |
| Assign From                                                           | GRACE TEO                                  | Assign Date     | 04/08/2021                       |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                         |                                            |                 |                                  |  |
| Make & Model                                                          |                                            | c.c             | 0                                |  |
| Engine No.                                                            | HIDDEN                                     | Year of Reg.    |                                  |  |
| Chassis No.                                                           |                                            | Colour          |                                  |  |
| Odometer                                                              | -                                          | Steering        |                                  |  |
| Brakes                                                                |                                            | Modification    |                                  |  |
| General                                                               |                                            |                 |                                  |  |
| <b>3. Conditions of Tyres</b>                                         |                                            |                 |                                  |  |
|                                                                       | Size                                       | Make            | Balance                          |  |
| R/H Front Tyre                                                        |                                            |                 | mm                               |  |
| L/H Front Tyre                                                        |                                            |                 | mm                               |  |
| R/H Rear Tyre                                                         |                                            |                 | mm                               |  |
| L/H Rear Tyre                                                         |                                            |                 | mm                               |  |
| <b>4. Description of Damages</b>                                      |                                            |                 |                                  |  |
|                                                                       |                                            |                 |                                  |  |
| <b>5. General Information</b>                                         |                                            |                 |                                  |  |
| Accident Date                                                         | 29/07/2021                                 | Inspection Date | <del>01/08/2021</del> 18/08/2021 |  |
| Survey held at                                                        | Blk 1 Sin Ming Industrial Sector C #01-135 |                 |                                  |  |
| Repairer                                                              | A T AUTO CONSULTANT                        |                 |                                  |  |
| <b>5a. Remarks</b>                                                    |                                            |                 |                                  |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.         |                                            |                 |                                  |  |
| B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                            |                 |                                  |  |