



Service Request Details

Claim

S1M03F2X

Reference

CS3/ASM21008261/c 

Loss Date

5 August 2021

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

5 Aug 2021 1:48:02 PM

Request Date

5 August 2021

Due Date

13 August 2021

Services

Pre-Repair Survey

Actions

Next Step

Agree to perform service

[Decline Work](#)



Vehicle Information

Incident Vehicle Registration #
SMK8926R

Make
TPVD HONDA

Model
SHUTTLE

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

PAY Daniel

zhihao.pay@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message