

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Reg. No: 199607	198R GST Reg. No. 19	9-96071	198-R	
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	R	Ref:	CS/AGI21008266/Uvf3n2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	D	ate:	27/09/2021	
			C	ode:	AGI	
1. Policy Particulars :- THIRD PARTY CLAIM					1	
	Insured Veh.	SJG 190D	Veh. Inspected		XB 9188M	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10011134/HA	Excess (\$)		0.00	
	Assign From	IVY RATILLA	Assign Date		05/08/2021	
2. Vehicle Particulars & Condition						
	Make & Model	NISSAN CWB45	c.c		13074	
	Engine No.	HIDDEN	Year of Reg.		2012	
	Chassis No.	CWB4CLP00151	Colour		GREEN	
	Odometer	348927 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	295/80 R22.5	AEOLUS		6 mm	
	L/H Front Tyre	295/80 R22.5	AEOLUS		6 mm	
	R/H Rear Tyre	295/80 R22.5 (D/D)	PIRELLI		6/6 6/6 mm	
	L/H Rear Tyre	295/80 R22.5 (D/D)	PIRELLI		6/6 6/6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	04/08/2021	Inspection Date		20/08/2021	
	Survey held at	IMPERIUM AUTOMOTIVE	•			
		25 KAKI BUKIT ROAD 4 #01-49 SYNERGY @ KB SINGAPORE 417800				
5a.	. Remarks					
	A)THE INSPECTION	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	D)III / IOOO IIDAIII	Estimate Days of Repair				
	Edilliato Dayo of Ropuli					

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: