

(09/11/13) wef.

ASS. REC. BY: Marcus

REF:

CS/AG121008286/U+3**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

LIA \$2087

Veh No:

GBEF0432

Yr Regn:

24/13/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA / cargo Mexi

Make:

FIAT Doblo

c.c

1598

Colour

white

A/C: Insured / Std / NI / NA

Sp. Reading

85509

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

2FA2630006C05405

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/60R16 Falken

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nexen

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

30/7/11

D.O.I.

6/8/11

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & Frt.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Dep 7500nett \$1412913/8/11 4/5 @ 10.800 confirmed with Susan.

(RED: 16787.20;60%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

8

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBE8043Z210730

Estimate

Customer

Page 01 - 02

Name: Auto & General Insurance (Singapore) Pte Ltd

Date: 04-08-21

Address: Motor Claims Department

Vehicle No: GBE8043Z

190 Clemenceau Avenue #03-01

Model/Make: Fiat Doblo Cargo

Singapore Shopping Centre Singapore 239924

Maxi 1.6 MTJ AMT Glaze

Item No.	Descriptions Of Parts		Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front	Bonnet <i>suc</i> 730.96	\$ 1,170.00	
2		Bonnet Inner Lock <i>suc</i>	\$ 145.00	X
3		Head Lamp 02 pcs (@ S\$862.40) <i>holder cro</i>	\$ 1,724.80	
4		Head Lamp Panel 02 pcs (@ S\$988.70) <i>n</i>	\$ 1,977.40	X
5		Centre Panel <i>DD/Bent</i> 485.11	\$ 945.00	
6		Bumper <i>del/torn</i> 855.30	\$ 1,245.50	
7		Bumper Clips 1 set <i>neu</i> 50	\$ 65.00	X
8		Bumper Reinforcement <i>Bent</i> 473.04	\$ 752.00	
9		Bumper Sponge <i>torn</i> 85.50	\$ 117.60	
10		Bumper Bracket 02 pcs (@ S\$171.80) <i>n n</i>	\$ 343.60	X
11		Bumper Lower Grille <i>torn</i> 485	\$ 685.00	X
12		Bumper Lower Grille Clips 1 set <i>n n</i>	\$ 65.00	X
13		Grille <i>del/torn</i> 361.55	\$ 484.70	
14		Grille "Fiat Logo" Motif <i>cro</i>	\$ 142.10	
15		Number Plate Garnish <i>Bent</i> 95.00	\$ 387.00	
16		Number Plate and Base <i>Bent</i>	\$ 48.00	SN 40 s/n
17		Radiator <i>holder cro</i> 717.49	\$ 854.30	X
18		Radiator Coolant 1 bottle <i>n ec</i>	\$ 45.00	SN 30 s/n
19		Aircon Condenser <i>p n n</i> 855	\$ 1,278.00	
20		Air Con Condensor Cowling <i>top torn</i>	\$ 285.00	
21	Rear Rh	Tailgate <i>DD</i>	\$ 1,895.90	
22		Tailgate Lock Lower <i>twi</i> 145	\$ 192.90	
23		Tailgate Weatherstrip <i>torn</i> 188.20	\$ 297.00	
24		Tailgate "FIAT Logo" Emblem <i>n n</i>	\$ 87.80	X
25		Tailgate "Professional" Emblem <i>neu</i> 145	\$ 163.50	
26		Tailgate "90" Emblem <i>neu</i>	\$ 97.50	
27		Tailgate "MultiJet" Emblem <i>neu</i> 82	\$ 119.60	
28		Tailgate "6 PAX" Sticker Rh <i>neu</i>	\$ 15.00	SN 10 s/n
29		Tailgate Glass Sealant <i>neu</i>	\$ 80.00	SN 40 s/n
30	Rear Lh	Tailgate <i>n</i>	\$ 2,395.00	X
31		Tailgate Weatherstrip <i>n n</i>	\$ 344.50	X
32		Tailgate "Doblo" Emblem <i>n n</i>	\$ 118.00	X
33		Tailgate "Maxi" Emblem <i>n n</i>	\$ 86.00	X
34		Tailgate "70 KM/H" Sticker <i>neu</i>	\$ 15.00	SN 10 s/n
35		Tailgate Glass Sealant <i>n n</i>	\$ 80.00	SN X
C/F Balance --->			\$ 18,747.70	

not Authorized

neu

6/8/21

2/5 @ 10,800

take photo after repair

8 days.

* Submit to insurance



M/s Liu's Brother Auto Engrg Wks

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBE8043Z210730

Estimate**Customer**

Page 01 - 02

Name: Auto & General Insurance (Singapore) Pte Ltd**Date:** 04-08-21**Address:** Motor Claims Department**Vehicle No:** GBE8043Z

190 Clemenceau Avenue #03-01

Model/Make: Fiat Doblo Cargo

Singapore Shopping Centre Singapore 239924

Maxi 1.6 MTJ AMT Glaze

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
----------	-----------------------	---------------------------------	------------------------------------

	B/F Balance --->	\$ 18,747.70	
36	Rear Bumper <i>589</i>	\$ 745.00	<i>X</i>
37	Bumper Clips 1 set <i>neu 50</i>	\$ 65.00	<i>X</i>
38	Bumper Reflector Rh <i>u1</i>	\$ 117.60	<i>X</i>
39	Bumper Reinforcement <i>341 461</i>	\$ 752.00	<i>X</i>
40	Bumper Reverse Sensor <i>101</i>	\$ 220.00	<i>SN 200 s/n</i>
41	Bumper Bracket 02 pcs (@ S\$258.10) <i>u1</i>	\$ 516.20	<i>X</i>
42	Bumper Towing Cover <i>u1</i>	\$ 95.00	<i>X</i>
43	End Panel Outer <i>R</i>	\$ 430.00	<i>X</i>
44	End Panel Inner <i>R</i>	\$ 295.00	<i>X</i>
45	End Panel Top Garnish <i>su</i>	\$ 347.70	<i>X</i>
46	End Panel Top Garnish Clips 1set <i>u1</i>	\$ 58.00	<i>SN X</i>
47	End Panel Sealant <i>u1</i>	\$ 50.00	<i>SN X</i>
48	Number Plate & Base <i>u1</i>	\$ 48.00	<i>SN X</i>
	"Corporate" Advertisement & Artwork <i>neu</i>	\$ 550.00	<i>SN 480 s/n</i>
	To check all (Fr & Rr) wiring & electrical component for proper function	\$ 180.00	<i>30</i>
	To remove & refix air con, re-fill air con gas & test for leakages	\$ 250.00	<i>100</i>
	To remove & replace radiator and conduct pressure test & bleed system	\$ 180.00	<i>max</i>
	Remove & reinstall Rear Rh & Lh Windscreen Glass to facilitate repairs	\$ 240.00	<i>100</i>
	Remove and refix rear Rh & Lh tailgate components & wiper mechanism	\$ 180.00	<i>60</i>
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 1,800.00	<i>1200</i>
	To putty & spray painting & including touch up paint on accident affected	\$ 1,600.00	<i>1280</i>
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 120.00	<i>90</i>

Total Parts & Labour of estimate for damaged vehicle

\$ 27,587.20

Total amount in Lump Sum Basis for repaired vehicle

SDLS: _____



M/s Liu's Brother Auto Engrg Wks

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

2-10999.45
 102
 3-9899.50
 S.N - 810.00
 L. 2860
 13569.50
 202
 10881

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

196N

Vehicle Details

Vehicle No.:

GBE8043Z

Vehicle to be Exported:

No

Intended Deregistration Date:

04 Aug 2021

Vehicle Make:

FIAT

Vehicle Model:

DOBLO CARGO MAXI 1.6 MTJ AMT GLAZE

Primary Colour:

Grey

Manufacturing Year:

2016

Engine No.:

263A50007570846

Chassis No.:

ZFA26300006C05405

Maximum Power Output:

-

Open Market Value:

\$19,091.00

Original Registration Date:

24 Mar 2016

First Registration Date:

24 Mar 2016

Transfer Count:

1

Actual ARF Paid:

\$955.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

23 Mar 2026

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

10

QP Paid:

\$45,036.00

COE Rebate Amount:

\$20,871.00

Total Rebate Amount:

\$20,871.00

The information contained herein is correct as at 04 Aug 2021

OK

**Goodyear Eagle F1
Asymmetric 5**

**Discussion for
Mercedes-Benz GLC-
Class**

Jaguar XE



Fiat Doblo

Price Range



Depreciation



2016



Vehicle Type



Search

Advanced Search

Home » Used Cars » ABS Bus Pte Ltd » Fiat Doblo Cargo Maxi 1.6A Multijet Glaze

Fiat Doblo Cargo Maxi 1.6A Multijet Glaze

Overview

Financial

Accessories

Similar

Research

Photos

Map

PREMIUM AD



Price	\$36,800		
Depreciation	\$7,980 /yr <small>View models with similar depre</small>	Reg Date	18-Mar-2016 (4yrs 7mths 11days COE left)
Mileage	N.A.	Manufactured	2015
Road Tax	N.A.	Transmission	Auto
Dereg Value	\$18,179 as of today (change)	Fuel Type	Diesel
COE	\$39,403	OMV	\$19,326
Engine Cap	1,598 cc	ARF	\$967
Curb Weight	1,500 kg	No. of Owners	1
Type of Vehicle	Van		

Features

View specs of the Fiat Professional Doblo Cargo Diesel (2014-2021)

Description

Auto Diesel Van Here. Unbelievable Condition. No Repairs Needed. Low Mileage And 1 Owner Only. In House Loan Available, High Trade In Price Offer. Call Our Friendly Salesman Now.

Category

Premium Ad Car

Status

Available for sale. Shortlist this car to get alerted whenever the price or availability changes.

Resources



Vehicle Evaluation


Afraid of lemons? Request to have this car evaluated professionally. Find out more

Compare

Car Valuation - Free



Price Chart



Click on the point to view the vehicle

Shortlist

Compare

Report Error

More

Seller Information

ABS Bus Pte Ltd

Customer Reviews



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)


Fiat Doblo

Price Range



Depreciation



2016



Vehicle Type



Search

Advanced Search

[Home](#) » [Used Cars](#) » [Direct Owners](#) » [Fiat Doblo Cargo Maxi 1.6A Multijet Glaze](#)

Fiat Doblo Cargo Maxi 1.6A Multijet Glaze

Overview

Financial

Accessories

Similar

Research

Photos

Map

[DIRECT OWNER](#)

Price	\$38,000	Lifespan	13-Jun-2036
Depreciation	\$7,830 /yr View models with similar depre	Reg Date	14-Jun-2016 (4yrs 10mths 7days COE left)
Mileage	N.A.	Manufactured	2016
Road Tax	N.A.	Transmission	Auto
Dereg Value	\$20,537 as of today (change)	Fuel Type	Diesel
COE	\$42,302	OMV	\$19,608
Engine Cap	1,598 cc	ARF	\$981
Curb Weight	1,500 kg	No. of Owners	1
Type of Vehicle	Van		

Features

Nice And Study Workhorse. Spacious Cabin Come Take A Look View specs of the Fiat Professional Doblo Cargo Diesel (2014-2021)

Description

For Interested Parties Please Kindly Contact

Category

Direct Owner Sale

Status

Available for sale. Shortlist this car to get alerted whenever the price or availability changes.

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more

Posted on: 27-Jul-2021 | Last Updated on: 27-Jul-2021

[Compare](#)


100% FREE
PAPERWORK
SUPPORT FOR
BOTH BUYER
& SELLER

Price Chart



[Click on the point to view the vehicle](#)

[Shortlist](#)
[Compare](#)
[Report Error](#)
[More](#)

Seller Information

Contact Person(s)	Benny
Contact No.	91820321

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	31/07/2021 13:29 (SGT)
Date of Accident	30/07/2021 16:40 (SGT)
Exact Location of Accident	PIE, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBE8043Z
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	GOLDBELL LEASING PTE LTD
Company Reg No	1XXXXX196N
Email Address	isaacngcl@gbl.com.sg
Mobile Phone No	(Phone) +65-87509916
Alternative Phone No	(Office) +65-64942897

VEHICLE PARTICULARS

Manufacturer	Fiat
Model	Doblo
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Auto
CC	1598

INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Type of Coverage	ThirdParty
Fleet Policy	Yes
Policy Number	D-21097582MFCV
Cover Note Number	-

DRIVER

Name of Driver	KOH SUSANI
NRIC No	SXXXX706A

Date Of Birth	02/02/1967
Occupation	Outdoor
Date Of Driving Pass	19/07/1988
Driving experience	33 YEARS
Gender	Male
Mobile Number	(Phone) +65-87509916
Alt. Phone Number	-
Email Address	isaacngcl@gbl.com.sg
Address	BLK 16 MARSILING LANE #12-207
Address complement	-
Postcode	730016
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

ON 30/07/2021, AT ABOUT 16:40HRS. I WAS DRIVING VEHICLE A, GBE8043Z TRAVELLING ALONG PIE AT THE MOST LEFT LANE. I EXITED THE EXPRESSWAY GOING TOWARDS JALAN BAHAR. APPROACHING A WHITE GIVE WAY LINE AT THE SLIP ROAD, I SAW VEHICLE B WAS IN A STOPPED STATIONARY AND I STOPPED BEHIND VEHICLE B. SUDDENLY I FELT AND IMPACT COMING FROM MY REAR AND MY VEHICLE MOVED TO THE FRONT AND CAUSED REAR ENDED TO VEHICLE B. I REALIZED VEHICLE C HAS REAR ENDED MY VEHICLE AND CAUSES CHAIN COLLISION ACCIDENT.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD6768J
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	MANI

Contact Number	(Phone) +65-83385330
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	2

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SMC7075T
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	NATASHA
Contact Number	(Phone) +65-81139594
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")


(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time 30.07.21 18.15

Witnessed by Reporting Centre Personnel MD NAZRIN

Sketch Plan

A-GPE8043Z
B-GBD6768J
C-SMC7075T

Describe Circumstances of the Accident

ON 30/07/2021, AT ABOUT 16:40 HRS. I WAS DRIVING VEHICLE A, GBE8043Z TRAVELLING ALONG PIE AT THE MOST LEFT LANE. I EXITED THE EXPRESSWAY GOING TOWARDS JALAN BAHAR. APPROACHING A WHITE GIVE WAY LINE AT THE SLIP ROAD, I SAW VEHICLE B WAS IN A STOPPED STATIONARY AND I STOPPED BEHIND VEHICLE B. SUDDENLY I FELT AN IMPACT COMING FROM MY REAR AND MY VEHICLE MOVED TO THE FRONT AND CAUSED REAR ENDED TO VEHICLE B. I REALISED VEHICLE C HAS REAR ENDED MY VEHICLE AND CAUSES CHAIN COLLISION ACCIDENT.

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time 30.07.21 18.15



Witnessed by Reporting Centre Personnel MD NAZKIN