



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21008337/Uvf3n2 Date: 19/08/2021 Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMJ 5323D	Veh. Inspected	SMZ 8088D	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10011174/JM	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	10/08/2021	
2. Vehicle Particulars & Condition				
Make & Model	BMW 116D (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WBA1V720705G87184	Colour	SILVER	
Odometer	73829 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/35 R19	PIRELLI	6 mm	
L/H Front Tyre	225/35 R19	PIRELLI	6 mm	
R/H Rear Tyre	255/30 ZR19	MICHELIN	6 mm	
L/H Rear Tyre	255/30 ZR19	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/08/2021	Inspection Date	10/08/2021	
Survey held at	BLK 15 KAKI BUKIT RD 4, BARTLEY BIZ CENTRE			
Repairer	ZOOM AUTOWERKS PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	