

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	SOMPO INSURAN	CE SINGAPORE PL		Ref:	CS/SMO21008372/Aqf3n2	
	50 RAFFLES PLAC SINGAPORE LAND	CE #03-03 D TOWERSINGAPORE 048623		Date:	14/10/2021	
				Code:	SMO	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMM 3874C	Veh. Inspected		SLG 4327C	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	CMTD2102351/IJH	Excess (\$)		0.00	
	Assign From	IRENE HENRY	Assign Date		11/08/2021	
2. Vehicle Particulars & Condition						
	Make & Model	MAZDA 3	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	JM6BM42A8G0346785	Colour		BLUE	
	Odometer	339035 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	205/60 R16	WINDFORCE		6 mm	
	L/H Front Tyre	205/60 R16	WINDFORCE		6 mm	
	R/H Rear Tyre	205/60 R16	WINDFORCE		6 mm	
	L/H Rear Tyre	205/60 R16	WINDFORCE		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	06/08/2021	Inspection Date	е	11/08/2021	
	Survey held at	eld at GREEN FOREST AUTOMOBILE				
		8 KAKI BUKIT AVENUE 4 #05-25 PREMIER @ KAKI BUKIT SINGAPORE 415875				
5a.	Remarks					
		N)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.		Estimate Days of Repair				
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days				