

Our Job Ref No : 305481597
Date : 12/08/21

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : Mr TAUFIKH
Vehicle Reg No. : SH 6621B CTPL

Fax :

08/06/21


The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: **NTUC** **SKG3839K**
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$998.62
 - (b) Labour Charges \$630.00
 - Total for Part-By-Part Repair Cost \$1,628.62**
 - (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost

3. Estimated normal period for repairs: 2 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : MS. LOKE YY
Tel : 62148355
Fax : 65468156

Signature : 
Name : Taufikh
Date : 30/8/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 12.08.2021

Time: 09:06:39

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305481597
REGN NO : SH 6621B
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 28.01.2021
DATE/TIME IN : 10.08.2021 10:00
ACCIDENT DATE : 06.08.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 28-01-0104-2029-A	VEHICLE NUMBER PLATE REAR	1	45.00	10.00	40.50
0002 04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00
0003 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60
0004 09-01-9999-0068-A	REVERSE SENSOR ASSY*	1	180.00	10.00	162.00
0005 04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52
0006 04-01-0104-1150-A	PROTECTOR MAT	1	50.00	2.00-	50.00

SUB-TOTAL : 998.62

JOB NATURE

0000 PB	PANEL BEATING SH6621B	350.00
0001 SP	SPRAYPAINT CHARGE	250.00
0002 20-204	REMOVE/REFIX REVERSE SENSOR	30.00

SUB-TOTAL : 630.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 12.08.2021

Time: 09:06:39

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305481597
REGN NO : SH 6621B
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 28.01.2021
DATE/TIME IN : 10.08.2021 10:0
ACCIDENT DATE : 06.08.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,628.62

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :