

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

NTEC (4/2)

Date: 10.08.2021

Time: 10:22:52

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305481596
 REGN NO : SHC1512Y
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID(G4)
 DATE OF REGN : 29.06.2017
 DATE/TIME IN : 10.08.2021 09:40
 ACCIDENT DATE : 06.08.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001	04-01-0302-2282-A	COVER REAR BUMPER^	1	458.60 25.00 343.95 <i>ky</i>
0002	04-01-0302-2267-G	BUMPER CLIPS	10	22.00 25.00 16.50 <i>ru</i>
0003	04-01-0302-2287-G	GUARD-REAR BUMPER CENTER	1	552.60 25.00 414.45 <i>de</i>
0004	04-01-0302-2288-G	REINFORCEMENT SUB-ASSY RE	1	318.80 25.00 239.10 <i>gun</i>

SUB-TOTAL : 1,014.00

JOB NATURE

0000	PB	PANEL BEATING	400.00	<i>350</i>
0001	SP	SPRAYPAINT CHARGE	300.00	<i>250 630</i>
0002	L	REMOVE/REFIX REAR W/SCREEN GLASS <i>reverse sensor</i>	80.00	<i>30</i>

SUB-TOTAL : 780.00

Jumani

MVA NAME & SIGNATURE

DATE: *10/8/21*

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE

DATE:

TOTAL : 1,794.00

*1060.95**4/8/850**02 days*

Tamplin 97495749
'up' 10/8/21 @ 1500
4/8 Resurvey after repair
Tamplin 11/8/21
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: