

ASS. REC. BY:

Tangkh

REF:

CS/CT/21008382/TIVC

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

939K.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SK 56880D.

Yr Regn:

2014, May

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volkswagen Jetta c.c 1390.

Colour

Hah.

A/C: Insured / Std / NI / NA

Sp. Reading

335344

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WVWZZZ/6ED M079418

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/40R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

12/8/21 0450pm

Survey held at

AP Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Rep. Format:

Lump Sum / L.B. (

## Estimation

Date 10/8/2021  
Vehicle SKJ 6880D  
Make/Model VOLKSWAGEN JETTA  
Chassis No. WVVZZZ16ZDM079418

No.	Description	Unit	Unit Price	Amount
	Parts Replacment			
1	FRONT HEADLAMP RH	1	\$	-
2	FRONT HEADLAMP LOWER BRACKET RH	1	\$	-
3	FRONT BUMPER	1	\$	-
4	FRONT BUMPER RETAINER RH	1	\$	-
5	FRONT BUMPER GRILLE	1	\$	-
6	FRONT BUMPER FOG LAMP RH	1	\$	-
7	FRONT BUMPER FOG LAMP GRILLE RH	1	\$	-
8	FRONT BUMPER REINFORCEMENT BAR	1	\$	-
9	FRONT FENDER RH	1	\$	-
10	FRONT FENDER COWLING RH	1	\$	-
11	FRONT DOOR RH	1	\$	-
12	FRONT DOOR HINGE TOP AND BOTTOM RH	2	\$	-
13	FRONT DOOR CHECKER RH	1	\$	-
14	FRONT DOOR INNER TRIM RH	1	\$	-
15	FRONT RIM RH	1	\$	-
16	FRONT ABSORBER RH	1	\$	-
17	FRONT LOWER ARM RH	1	\$	-
18	FRONT KNUCKLE RH	1	\$	-
19	FRONT KNUCKLE BEARING RH	1	\$	-
20	FRONT BEARING HUB RH	1	\$	-
			Total	\$ -
			Less 10%	\$ -
			<b>Total</b>	<b>\$ -</b>

	S/Nett Items			
1	FRONT BUMPER CLIP SET	1	120	\$ 120.00
2	FRONT FENDER COWLING CLIP SET	1	120	\$ 120.00
3	FRONT DOOR INNER TRIM CLIP SET	1	120	\$ 120.00
4	FRONT TYRE RH	1	800	\$ 800.00
			<b>Total</b>	<b>\$ 1,160.00</b>

	LABOUR				
1	PANEL BEATING ON AFFECTED AREAS	1	1200	\$ 600	1,200.00
2	SPRAY PAINT ON AFFECTED AREAS	1	1200	\$ 800	1,200.00
3	TO CHECK WIRING AND HEADLAMP FOCUS	1	120	\$ 30	120.00
4	TO CHECK WHEEL ALIGNMENT AND ADJUST	1	120	\$ 80	120.00
5	TO RNR UNDERCARRIAGE	1	250	\$ 1007 parts	250.00
6	TO CHECK WHEEL BALANCING	1	120	\$ 30	120.00
7	TO RNR REAR FRONT DOOR MECHANISM	1	250	\$ x	250.00
				<b>Total Labour</b>	<b>\$ 3,260.00</b>
				<b>Parts Replacement Amount</b>	<b>\$ 1,160.00</b>
				<b>Total Amount</b>	<b>\$ 4,420.00</b>

Taulhin 97415749  
 'up' 12/8/21 @ 1650  
 2/5 Resurvey after repair  
 Taulhin 01/10/2021  
 # 5 days

**LKK Auto Consultants** hence notify  
**the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	780F
<b>Vehicle Details</b>	
Vehicle No.:	SKJ6880D
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Aug 2021
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	JETTA 1.4 TSI AT 1623G5
Primary Colour:	Black
Manufacturing Year:	2013
Engine No.:	CAXD42575
Chassis No.:	WVWZZZ16ZDM079418
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$20,834.00
Original Registration Date:	16 May 2014
First Registration Date:	16 May 2014
Transfer Count:	1
Actual ARF Paid:	\$11,168.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 May 2024
PARF Rebate Amount:	\$6,700.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	15 May 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$60,002.00
COE Rebate Amount:	\$16,242.00
<b>Total Rebate Amount:</b>	<b>\$22,942.00</b>

The information contained herein is correct as at 06 Aug 2021

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	06/08/2021 14:56 (SGT)
Date of Accident	05/08/2021 11:45 (SGT)
Exact Location of Accident	Dunearn Rd, Singapore
Additional Location Information	DUNEARN ROAD AFTER VANDA ROAD
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKJ6880D
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	RAYMOND TAN KAY CHON (CHEN JIACONG)
NRIC No	SXXXX780F
Email Address	SPIDERRAY78@GMAIL.COM
Mobile Phone No	(Phone) +65-81983304
Alternative Phone No	(Home) +65-81983304

#### VEHICLE PARTICULARS

Manufacturer	Volkswagen
Model	Jetta
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire
Transmission	Auto
CC	1390

#### INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5101848476-03
Cover Note Number	-

#### DRIVER

Name of Driver	RAYMOND TAN KAY CHON (CHEN JIACONG)
NRIC No	SXXXX780F

Date Of Birth	29/11/1978
Occupation	Outdoor
Date Of Driving Pass	06/03/1999
Driving experience	22 YEARS AND 5 MONTHS
Gender	Male
Mobile Number	(Phone) +65-81983304
Alt. Phone Number	(Home) +65-81983304
Email Address	SPIDERRAY78@GMAIL.COM
Address	BLK 130 PUNGGOL WALK #04-14
Address complement	-
Postcode	828776
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Change/cross lane
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO ATTACHMENT

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKP6679M
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-

Postcode  
Insurance Company Name  
Nature Of Damage  
Details of property damaged in accident  
No. Of Passenger (Including Driver)

-  
-  
-  
-  
-

#### INJURED PERSONS DETAILS

##### INJURED 1

Name of injured person  
Gender  
Phone No  
Address  
Address Complement  
Post Code  
Approximate Age Years Old  
Injuries Sustained  
Injured person in which vehicle?  
Were seat belts worn?  
Was this injured conveyed to hospital by ambulance?

RAYMOND TAN KAY CHON (CHEN JIACONG)  
-  
-  
-  
-  
-  
-  
-  
SKJ6880D  
Yes  
No

# SKETCH PLAN

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of the report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)  
I understand, acknowledge, agree and consent that:  
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purpose(s) of:  
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;  
(ii) investigating the accident and/or my claims;  
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;  
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to being about delivery of the same as well as on the external cover of envelopes/packets/packages); and/or  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");  
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and  
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Not used  
After Vandalised

SHELL



Vehicle A: SKJ688D  
Vehicle B: SKP 6679M



On 5/8/2021 at around 11:55am I was travelling along  
Dunearn Road just after Vanda Road on centre line when  
suddenly vehicle SKP 6679M from the 1st lane on my right  
swerved abruptly onto my lane and collided on my vehicle  
right portion. We stopped the vehicle and exchange photos,  
the driver of SKP 6679M explained that they are turning into  
Shell station thus resulting in the accident.

We declare the foregoing particulars are true in every respect.

Witnessed by Reporting Centre  
Personnel