

(08/11/13) wef
ASS. REC. BY: Marcus

REF:

CC6/A1621008392/4653

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: XE62402
at Workshop m/s R
of _____
Insured: SM MS-1P3X
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$148k.
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: days Res.: Yes or No
Lum Sum: % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS C RPK
Vehicle: IN / OUT
Date: _____ Person Contacted: L1A631707

Veh No: XE62402 Yr Regn: 09/03/21
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or (M)
Make: CAMC C.C. 11812
Colour: white A/C: Insured / Std / NI / NA
Sp. Reading: 60253 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: L25N2DD36LB018590
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Order / Jammed / Leaked / Burnt or
Brake: Order / Jammed / Leaked / Burnt or
Modi: M/L / S/Rim / STD A/Rim or
Tyre Size: F: 295 / R 222.5
R: Aeolus
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Anneite
Front: 6 Rear: 6/66/6
R/Bal. mm R/Bal. mm
L/Bal. mm L/Bal. 6/6 6/6 mm
D.O.A. 6/18/21 D.O.I. 11/8/21
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear O/S 2 ft 0/5
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
New Trade \$158k.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I. (\$))

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	808K
Vehicle Details	
Vehicle No.:	XE6240Z
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Aug 2021
Vehicle Make:	CAMC
Vehicle Model:	HN3251X40C3M6
Primary Colour:	White
Manufacturing Year:	2020
Engine No.:	CM6D2840060120D04169
Chassis No.:	LZ5N2DD36LB018590
Maximum Power Output:	-
Open Market Value:	\$71,030.00
Original Registration Date:	09 Mar 2021
First Registration Date:	09 Mar 2021
Transfer Count:	0
Actual ARF Paid:	\$3,552.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	08 Mar 2031
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$33,125.00
COE Rebate Amount:	\$31,707.00
Total Rebate Amount:	\$31,707.00

The information contained herein is correct as at 11 Aug 2021

OK