

|   |   |          |   |   |   |   |        |   |   |             |
|---|---|----------|---|---|---|---|--------|---|---|-------------|
| ⏪ | < | 1 of 2 ? | > | ⏩ | ↺ | ↻ | 100% ▼ | 🖨 | 📄 | Find   Next |
|---|---|----------|---|---|---|---|--------|---|---|-------------|



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                                                                                                                                |                             |                           |            |  |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|---------------------------|------------|--|
| AIG ASIA PACIFIC INSURANCE PTE LTD                                                                                                                                                                                                               |                             | Ref: CS3/AIG21008411/Gqf3 |            |  |
| 78 SHENTON WAY #09-16                                                                                                                                                                                                                            |                             | Date: 11/08/2021          |            |  |
| AIG BUILDING                                                                                                                                                                                                                                     |                             |                           |            |  |
| SINGAPORE 079120                                                                                                                                                                                                                                 |                             | Code: AIG                 |            |  |
| 1. Policy Particulars :- (THIRD PARTY CLAIM)                                                                                                                                                                                                     |                             |                           |            |  |
| Insured Veh.                                                                                                                                                                                                                                     | GBL 2191G                   | Veh. Inspected            | YN 4707X   |  |
| Policy No.                                                                                                                                                                                                                                       |                             | Coverage (\$)             | 0.00       |  |
| Claim No.                                                                                                                                                                                                                                        | 1627444522SG                | Excess (\$)               | 0.00       |  |
| Assign From                                                                                                                                                                                                                                      | DIVYASHNI SUBRAMANIAM       | Assign Date               | 11/08/2021 |  |
| 2. Vehicle Particulars & Condition                                                                                                                                                                                                               |                             |                           |            |  |
| Make & Model                                                                                                                                                                                                                                     | c.c                         |                           | 0          |  |
| Engine No.                                                                                                                                                                                                                                       | HIDDEN                      | Year of Reg.              |            |  |
| Chassis No.                                                                                                                                                                                                                                      |                             | Colour                    |            |  |
| Odometer                                                                                                                                                                                                                                         | -                           | Steering                  |            |  |
| Brakes                                                                                                                                                                                                                                           |                             | Modification              |            |  |
| General                                                                                                                                                                                                                                          |                             |                           |            |  |
| 3. Conditions of Tyres                                                                                                                                                                                                                           |                             |                           |            |  |
|                                                                                                                                                                                                                                                  | Size                        | Make                      | Balance    |  |
| R/H Front Tyre                                                                                                                                                                                                                                   |                             |                           | mm         |  |
| L/H Front Tyre                                                                                                                                                                                                                                   |                             |                           | mm         |  |
| R/H Rear Tyre                                                                                                                                                                                                                                    |                             |                           | mm         |  |
| L/H Rear Tyre                                                                                                                                                                                                                                    |                             |                           | mm         |  |
| 4. Description of Damages                                                                                                                                                                                                                        |                             |                           |            |  |
|                                                                                                                                                                                                                                                  |                             |                           |            |  |
| 5. General Information                                                                                                                                                                                                                           |                             |                           |            |  |
| Accident Date                                                                                                                                                                                                                                    | 07/08/2021                  | Inspection Date           | 12/08/2021 |  |
| Survey held at                                                                                                                                                                                                                                   | 160 Sin Ming Drive #05-17   |                           |            |  |
| Repairer                                                                                                                                                                                                                                         | HIAP LEK AUTOMOBILE TRADING |                           |            |  |
| 5a. Remarks                                                                                                                                                                                                                                      |                             |                           |            |  |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.<br>THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.<br>C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. |                             |                           |            |  |