



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                          |                                                                                                                                        |                                                                                                           |                                                              |                |
|--------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------|--------------------------------------------------------------|----------------|
| AXA INSURANCE PTE LTD<br>8 SHENTON WAY #24-01<br>AXA TOWERSINGAPORE 068811<br>ATTN:VALE OH |                                                                                                                                        |                                                                                                           | Ref: CC4/ASM21008412/Tea3q2<br>Date: 12/07/2022<br>Code: ASM |                |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                          |                                                                                                                                        |                                                                                                           |                                                              |                |
|                                                                                            | <b>Insured Veh.</b>                                                                                                                    | SLG 4539H                                                                                                 | <b>Veh. Inspected</b>                                        | GBJ 5431E      |
|                                                                                            | <b>Policy No.</b>                                                                                                                      | GA551503                                                                                                  | <b>Coverage (\$)</b>                                         | 0.00           |
|                                                                                            | <b>Claim No.</b>                                                                                                                       | S1M03FCB                                                                                                  | <b>Excess (\$)</b>                                           | 0.00           |
|                                                                                            | <b>Assign From</b>                                                                                                                     |                                                                                                           | <b>Assign Date</b>                                           | 11/08/2021     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                              |                                                                                                                                        |                                                                                                           |                                                              |                |
|                                                                                            | <b>Make &amp; Model</b>                                                                                                                | TOYOTA DYNA                                                                                               | <b>c.c</b>                                                   | 2982           |
|                                                                                            | <b>Engine No.</b>                                                                                                                      | HIDDEN                                                                                                    | <b>Year of Reg.</b>                                          | 2019           |
|                                                                                            | <b>Chassis No.</b>                                                                                                                     | JTFAT35YX0K213092                                                                                         | <b>Colour</b>                                                | BLUE           |
|                                                                                            | <b>Odometer</b>                                                                                                                        | -                                                                                                         | <b>Steering</b>                                              | IN ORDER       |
|                                                                                            | <b>Brakes</b>                                                                                                                          | IN ORDER                                                                                                  | <b>Modification</b>                                          | NIL            |
|                                                                                            | <b>General</b>                                                                                                                         | GOOD                                                                                                      |                                                              |                |
| <b>3. Conditions of Tyres</b>                                                              |                                                                                                                                        |                                                                                                           |                                                              |                |
|                                                                                            |                                                                                                                                        | <b>Size</b>                                                                                               | <b>Make</b>                                                  | <b>Balance</b> |
|                                                                                            | <b>R/H Front Tyre</b>                                                                                                                  | 195 R15                                                                                                   | LINAM                                                        | 5 mm           |
|                                                                                            | <b>L/H Front Tyre</b>                                                                                                                  | 195 R15                                                                                                   | LINAM                                                        | 5 mm           |
|                                                                                            | <b>R/H Rear Tyre</b>                                                                                                                   | 155 R12 (D)                                                                                               | LINAM                                                        | 5/5 mm         |
|                                                                                            | <b>L/H Rear Tyre</b>                                                                                                                   | 155 R12 (D)                                                                                               | LINAM                                                        | 5/5 mm         |
| <b>4. Description of Damages</b>                                                           |                                                                                                                                        |                                                                                                           |                                                              |                |
|                                                                                            | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION & N/S BODY AND UNDERCARRIAGE.<br><br>DAMAGES SEE DETAILS.                       |                                                                                                           |                                                              |                |
| <b>5. General Information</b>                                                              |                                                                                                                                        |                                                                                                           |                                                              |                |
|                                                                                            | <b>Accident Date</b>                                                                                                                   | 07/08/2021                                                                                                | <b>Inspection Date</b>                                       | 16/09/2021     |
|                                                                                            | <b>Survey held at</b>                                                                                                                  | RICO 60 AUTO SERVICES PTE LTD<br>8 KAKI BUKIT AVENUE 4<br>#02-24 PREMIER @ KAKI BUKIT<br>SINGAPORE 415875 |                                                              |                |
| <b>5a. Remarks</b>                                                                         |                                                                                                                                        |                                                                                                           |                                                              |                |
|                                                                                            | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                           |                                                              |                |
| <b>5b. Estimate Days of Repair</b>                                                         |                                                                                                                                        |                                                                                                           |                                                              |                |
|                                                                                            | ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                                           | 16 Working Days                                              |                |