

CC4/ASUN 21008412/ raz

TOTAL

RICO60

AUTO SERVICES

Rico 60 Auto Services Pte Ltd
Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875
Email: claims@rico60.com
Tel: 6286 6060 Fax : 6286 7060

RICO Office Use Only

Parts -%25	
SN	
Labour	
TOTAL	
LUMSUM	
ERV	51K

TO: AXA

Vehicle No : GBJ 5431 E

Make & Model : TOYOTA DYNA

DATE: 10/8/2021

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE
1	FRONT PANEL	1	\$ 1,194.30	\$ 1,194.30 1,194.30
2	FRONT PANEL EMBLEM(DYNA)	1	\$ 154.10	\$ 154.10 154.10
3	FRONT WIPER PANEL	1	\$ 754.60	\$ 754.60 754.60
4	FRONT WIPER PANEL GARNISH	1	\$ 417.00	\$ x 417.00
5	FRONT WIPER ARM	2	\$ 178.90	\$ x 357.80
6	FRONT WIPER ARM COVER	2	\$ 45.00	\$ x 90.00
7	FRONT WIPER BLADE	2	\$ 86.70	\$ x 173.40
8	FRONT GRILLE	1	\$ 695.20	\$ 695.20 695.20
9	FRONT GRILLE LOGO	1	\$ 89.00	\$ 89.00 89.00
10	HEAD LAMP	2	\$ 1,121.00	\$ 2,242.00
11	HEAD LAMP LOWER RUBBER	2	\$ 66.50	\$ 133.00
12	FRONT BUMPER	1	\$ 798.90	\$ 798.90 798.90
13	FRONT BUMPER BRACKET	2	\$ 457.90	\$ 915.80
14	FRONT BUMPER FOG LAMP COVER	1	\$ 56.00	\$ 56.00 56.00
15	FRONT CORNER PANEL LH	1	\$ 589.00	\$ 589.00 589.00
16	FRONT CORNER PANEL BRACKET LH	1	\$ 112.00	\$ 112.00 112.00
17	CABIN ROLLER BAR	1	\$ x 1,254.00	\$ 1,254.00
18	CABIN ROLLER BAR MOUNTING	2	\$ 275.00	\$? 550.00
19	CABIN ROLLER BAR TOP BRACKET	2	\$ 177.30	\$? 354.60
20	CABIN ROLLER BAR HOLDER	2	\$ 457.90	\$? 915.80
21	FRONT SIDE MIRROR LH	1	\$ 578.50	\$ x 578.50
22	FRONT PARKING MIRROR LH	1	\$ 379.80	\$ x 379.80
23	FRONT SIDE MIRROR BRACKET LH	1	\$ 1,474.00	\$? 1,474.00
24	FRONT SIDE MIRROR BRACKET BOTTOM COVER LH	1	\$ 87.00	\$? 87.00
25	FRONT WINDSCREEN	1	\$ 1,564.50	\$ 1,564.50 1,564.50
26	FRONT WINDSCREEN MOULDING	1	\$ 279.80	\$ 279.80 279.80

27	FRONT DOOR OUTER PILLAR LH		1	\$ 1,254.00	\$ bt 1,254.00
28	FRONT DOOR INNER PILLAR LH		1	\$ 794.50	\$ bt 794.50
29	FRONT DOOR LH		1	\$ 1,794.20	\$ bt 1,794.20
30	FRONT DOOR GLASS LH		1	\$ 692.70	\$ x 692.70
31	FRONT DOOR QUARTER PLATE LH		1	\$ 155.90	\$ x 155.90
32	FRONT DOOR OUTER MOULDING LH		1	\$ 159.80	\$ de 159.80
33	FRONT DOOR INNER MOULDING LH		1	\$ 158.10	\$ de 158.10
34	FRONT DOOR OUTER HANDLE LH		1	\$ 257.10	\$ de 257.10
35	FRONT DOOR HINGE LH		2	\$ 120.00	\$ bt 240.00
36	FRONT DOOR CHECKER LH		1	\$ 136.50	\$ bt 136.50
37	FRONT DOOR INNER LOCK LH		1	\$ 396.40	\$ pr 396.40
38	FRONT DOOR LOCK CATCH LH		1	\$ 46.00	\$ bt 46.00
39	FRONT DOOR WEATHERSTRIP LH		1	\$ 198.00	\$ at 198.00
40	FRONT DOOR CHANNEL LH		1	\$ 89.00	\$ de 89.00
41	FRONT DOOR CHANNEL SEAL LH		1	\$ 178.90	\$ ner 178.90
42	FRONT DOOR INNER TRIM LH		1	\$ 591.50	\$ de 591.50
43	FRONT DOOR POWER WINDOW SWICTH LH		1	\$ 369.30	\$ dis 369.30
44	FRONT DOOR REGULATOR MOTOR LH		1	\$ 475.90	\$? 475.90
45	FRONT DOOR REGULATOR GEAR LH		1	\$ 321.00	\$ bt 321.00
46	FRONT DOOR TOP RAILING HANDLE LH		1	\$ 254.30	\$ x 254.30
47	FRONT DOOR INNER OPENER HANDLE LH		1	\$ 218.00	\$ as 218.00
48	FRONT DOOR FRAME WEATHERSTRIP LH		1	\$ 254.00	\$ ner 254.00
49	FRONT DOOR SIDE RUBBER LH		1	\$ 100.00	\$? 100.00
50	FRONT DOOR BOTTOM RUBBER LH		1	\$ 100.00	\$? 100.00
51	FRONT DOOR LOWER STEP GARNISH		2	\$ 498.70	\$ ner 997.40
44	CABIN CARRIER FRONT PANEL		1	\$ 4,854.00	\$ R 4,854.00
52	CABIN REAR PILLAR LH		1	\$ 1,542.00	\$ R 1,542.00
53	CABIN REAR PILLAR EMBLEM (D4D)		1	\$ 96.80	\$ ner 96.80
54	CABIN BACK PANEL		1	\$ 987.30	\$ XR 987.30
55	CABIN REAR OPENER HANDLE		1	\$ 254.00	\$? 254.00
56	CABIN REAR OPENER LINK		1	\$ 122.00	\$? 122.00
57	CABIN REAR OPENER LOCK		2	\$ 417.60	\$ R ? 835.20
58	CABIN REAR OPENER BOTTOM LOCK MOUNTING		2	\$ 189.00	\$ x 378.00
59	CABIN REAR SUPPORT PANEL		1	\$ 890.00	\$ x 890.00
60	CABIN WHEEL ARCH PANEL LH		1	\$ 854.00	\$ bt 854.00
61	CABIN WHEEL ARCH PANEL SIDE RUBBER LH		1	\$ 102.40	\$ de 102.40
62	REAR MUDGUARD LH		1	\$ 372.40	\$ bt 372.40
63	FRONT ABSORBER <i>photo</i>	<i>LH bt</i> <i>RH?</i>	2	\$ 207.70	\$ bt 415.40
64	FROTN ABSORBER TOP MOUNTING <i>LH bt</i> <i>RH?</i> <i>photo</i>		2	\$ 90.00	\$ 180.00
65	FRONT UPPER ARM <i>photo</i>	<i>LH bt</i> <i>RH?</i>	2	\$ 1,720.50	\$ 3,441.00
66	FRONT LOWER ARM <i>photo</i>	<i>LH bt</i> <i>RH?</i>	2	\$ 1,029.60	\$ 2,059.20
67	FRONT KNUCKLE ARM <i>photo</i>	<i>LH bt</i> <i>RH?</i>	2	\$ 845.00	\$ 1,690.00

68	FRONT WHEEL BEARING	LH RH ?	2	\$	256.00	\$	512.00
69	STEERING TIE ROD	LH RH ?	2	\$	369.30	\$	738.60
70	STEERING TIE ROD END	LH RH ?	2	\$	351.90	\$	703.80
71	STEERING RICK	?	1	\$	2,545.00	\$	2,545.00
72	FLOOR PANEL		1	\$	1,658.00	\$?	1,658.00
73	FLOOR PANEL MAT		1	\$	1,215.00	\$ de -	1,215.00
74	DASH BOARD	photo	1	\$	1,532.00	\$ de	1,532.00
75	DASH BOARD SIDE SPEAKER LH		1	\$	258.30	\$?	258.30
76	DASH BOARD SIDE SPEAKER COVER LH		1	\$	112.10	\$?	112.10
77	DASH BOARD GLOOVE BOX		1	\$	574.00	\$?	574.00
78	DASH BOARD GLOOVE BOX LOWER COVER		1	\$	585.00	\$?	585.00
79	DASH BOARD CENTER CONSOLE BOX		1	\$	317.20	\$ x	317.20
80	DASH BOARD INNER BEAM		1	\$	1,542.00	\$?	1,542.00
81	AIR CON COOLING COIL ASSY		1	\$	2,854.00	\$?	2,854.00
82	STEERING WHEE AIR BAG		1	\$	1,421.00	\$ al -	1,421.00
83	PASSENGER AIR BAG		1	\$	1,254.00	\$ al -	1,254.00
84	FRONT SEAT BELT	LH ? , RH yes	2	\$	954.00	\$	1,908.00
85	AIR CON CONDENSER		1	\$	1,452.00	\$ bt -	1,452.00
86	DRIVER SEAT		1	\$	658.00	\$ x	658.00
87	PASSENGER SEAT		1	\$	845.00	\$ x	845.00
88	CONDENSER BRACKET		1	\$	485.00	\$ bt -	485.00
89	CONDENSER FAN COWLING ASSY		1	\$	589.00	\$ one -	589.00
90	RADIATOR		1	\$	2,349.20	\$?	2,349.20
91	RADIATOR FAN COWLING		1	\$	217.70	\$?	217.70
92	RADIATOR FAN BLADE		1	\$	96.70	\$?	96.70
93	REAR DIESEL TANK		1	\$	1,254.00	\$? ?	1,254.00
94	REAR DIESEL TANK BRACKET		2	\$	216.00	\$? ?	432.00
95	CENTER LONG SHAFT		1	\$	2,117.10	\$?	2,117.10
96	RAER WHEEL MUDGUARD RH		2	\$	241.00	\$ bt -	482.00
97	REAR AXLE BEAM		1	\$	3,557.30	\$?	3,557.30
98	REAR ABSORBER		2	\$	317.20	\$?	634.40
99	REAR EXHAUST PIPE		1	\$	652.00	\$?	652.00
100	REAR EXHAUST CENTER PIPE		1	\$	854.00	\$?	854.00
101	EXHAUST CATALYTIC CONVERTER PIPE		1	\$	1,245.00	\$?	1,245.00

Subtotal : \$ 83,166.70

Less 25% \$ 20,791.68

Parts Total : \$ 62,375.03

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE
1	FRONT NUMBER PLATE	bt - 1	\$ 80.00	\$ 30 80.00
2	FRONT BUMPER CLIPS	3044 1	\$ 40.00	\$ 40.00

3	FRONT DOOR COMPANY LETTERING	new ✓	2	\$	60.00	\$ 60	120.00
4	FRONT PANEL SEALANT	new ✓	1	\$	80.00	\$ 30	80.00
5	FRONT WIPER PANEL GARNISH CLIP		1	\$	50.00	\$ X	50.00
6	FRONT GRILLE CLIP	new ✓	1	\$	40.00	\$ 20	40.00
7	HEAD LAMP CLIP	new ✓	1	\$	40.00	\$ 20	40.00
8	FRONT CORNER PANEL CLIP		1	\$	50.00	\$ X	50.00
9	FRONT DOOR OUTER PILLAR SEALANT		1	\$	80.00	\$ 340	80.00
10	FRONT DOOR INNER PILLAR SEALANT		1	\$	80.00	\$ 5	80.00
11	FRONT DOOR QUARTER PLATE CLIP		1	\$	30.00	\$ X	30.00
12	FRONT DOOR INNER TRIM CLIP		1	\$	50.00	\$ 20 new	50.00
13	FRONT DOOR SIDE RUBBER CLIP		1	\$	40.00	\$ 7	40.00
14	FRONT DOOR BOTTOM RUBBER CLIP		1	\$	40.00	\$ 30	40.00
15	FRONT DOOR LOWER STEP GARNISH CLIP		1	\$	40.00	\$ 5	40.00
16	CABIN REAR PILLAR SEALANT		1	\$	80.00	\$ 30	80.00
17	CABIN BACK PANEL SEALANT		1	\$	80.00	\$ 5	80.00
18	CABIN WHEEL ARCH PANEL SEALANT		1	\$	80.00	\$ 20 new	80.00
19	REAR MUDGUARD CLIP		1	\$	50.00	\$ X	50.00
20	REAR MUDGUARD MUDFLAP		2	\$	40.00	\$ X	80.00
21	RADIATOR COOLANT		1	\$	60.00	\$?	60.00
22	REAR CANOPY BOX ASSY	to check & dismantle	1	\$	4,500.00	\$?	4,500.00
23	RIVET		1	\$	150.00	\$ 50	150.00
24	FRONT TYRE	punctured ✓ 70%	2	\$	200 330.00	\$	660.00
25	FRONT RIM	to ?	2	\$	200 400.00	\$	800.00
26	REAR RIM	ht ✓	2	\$	150 350.00	\$	700.00
27	REAR TYRE	punctured ✓ 70%	2	\$	150 300.00	\$	600.00

SPECIAL NETT \$ **8,700.00**

LABOUR		PRICE
PANEL BEATING, REMOVAL AND REPLACING PARTS	1800	\$ 3,500.00
TO SPRAY PAINT AFFECTED AREA	1600	\$ 3,200.00
TO SPRAY TUFF COAT	150	\$ 600.00
WIRING, BULB CHECKING	30	\$ 600.00
REMOVE AND REFIX UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR		\$ 100 600.00
REMOVE AND REFIX FRONT WIRE HARNESS	mt ? 200	\$ 1,200.00
REMOVE AND REFIX DASHBOARD AND INTERNAL WIRING	200	\$ 600.00
REMOVE AND REFIX AUDIO SYSTEM	? 60	\$ 150.00
REMOVE AND REFIX FRONT WINDSCREEN	120	\$ 150.00
CONDUCT WATER LEAKAGE TEST	30	\$ 200.00
TRANSFER FRONT DOOR MECHANISM	60	\$ 100.00

REMOVE & REINSTALL CABIN REAR GLASS		\$ X 120.00
REMOVE AND INSTALL RADIATOR AND REFILL COOLANT AND HIGH PRESSURE TEST	photo	\$ 120? 180.00
REMOVE AND INSTALL CONDENSER AND REFILL AIRCON GAS		\$ 100 150.00
REMOVE AND INSTALL FRONT UNDER CARRIAGE		\$ 300 600.00
REMOVE AND INSTALL REAR UNDER CARRIAGE	photo?	\$ 300 800.00
TO CHECK FOUR WHEEL ALIGHMENT		\$ 80 150.00
REMOVE AND INSTALL FUEL TANK	photo. 15	\$? 300.00
	LABOUR TOTAL	\$ 13,200.00
	Total Parts Cost	\$ 71,075.03
	Total Labour Cost	\$ 13,200.00
	Total Repair Cost	\$ 84,275.03

APPROVED DETAILS
NO. OF WORKING DAYS
PART BY PART OR LUMP SUM
DATE & TIME OF SURVEY
SURVEYED BY
CONTACT NUMBER
FAX NUMBER

Tanjoh 97495749
 - WP 16/9/21 @ 445pm
 c/s Repair after repair
 Tanjoh & Wharton
 16 days
 To check repair limit

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:


> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Business	
Owner ID:	078E	
Vehicle Details		
Vehicle No.:	GBJ5431E	
Vehicle to be Exported:	No	
Intended Deregistration Date:	10 Aug 2021	
Vehicle Make:	TOYOTA	
Vehicle Model:	DYNA 150 5MT	
Primary Colour:	Blue	
Manufacturing Year:	2019	
Engine No.:	1KD2853402	
Chassis No.:	JTFAT35YX0K213092	
Maximum Power Output:	-	
Open Market Value:	\$27,082.00	
Original Registration Date:	27 May 2019	
First Registration Date:	27 May 2019	
Transfer Count:	0	
Actual ARF Paid:	\$1,355.00	
Intended PARF Rebate Details		
PARF Eligibility:	No	
PARF Eligibility Expiry Date:	-	
PARF Rebate Amount:	\$0.00	
Intended COE Rebate Details		
COE Expiry Date:	26 May 2029	
COE Category:	C - Goods Vehicle & Bus	
COE Period(Years):	10	
PQP Paid:	\$25,497.00	
COE Rebate Amount:	\$19,869.00	
Total Rebate Amount:	\$19,869.00	

The information contained herein is correct as at 10 Aug 2021

OK



Home » Used Cars » Car (S) Pte Ltd » Toyota Dyna 150 3.0M

Toyota Dyna 150 3.0M

[Overview](#)
[Financial](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)

PREMIUM AD



Price	\$71,800	Lifespan	19-Jun-2039
Depreciation	\$9,250 /yr View models with similar depre	Reg Date	20-Jun-2019 (7yrs 9mths 3days COE left)
Mileage	N.A.	Manufactured	2019
Road Tax	N.A.	Transmission	Manual
Dereg Value	\$18,981 as of today (change)	Fuel Type	Diesel
COE	\$24,455	OMV	\$27,082
Engine Cap	2,982 cc	ARF	\$1,355
Curb Weight	1,740 kg	No. of Owners	1
Type of Vehicle	Truck		

Features

We Only Give You Wide Variety Of Vehicle, Trust, Confident And Best Service! View specs of the Toyota Dyna 150 Diesel (2014)

Accessories

Free High Box With Two Sliding Doors! Expensive Full Leather Seat. New Paintwork And Servicing.

Description

1 OWNER! Agent Unit Yet Clocked Super Low Mileage. 3 Months Warranty Guaranteed With Free Servicing! Flexible Loan Or Cash Deal Also Possible. Trade In Avail. Call The Below Handphone Number Now For Your Concern And Let Us Help You.

Category

Premium Ad Car

Status

Available for sale. Shortlist this car to get alerted whenever the price or availability changes.

Resources



Car Valuation - Free


Find out the market value of your existing c

[Compare](#)



Price Chart

Summary



Click on the point to view the vehicle

[Shortlist](#) [Compare](#) [Report Error](#)

[More](#)

Seller Information

Car (S) Pte Ltd

★ PREMIUM DEALER 2021 ★

328 vehicles for sale 189 sold in past 3 mths

39 Woodlands Close #07-K1, #08-04
Mega @ Woodlands
Tel: 63863322

Linam. 195K15
155K17.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	12/08/2021 15:06 (SGT)
Date of Accident	07/08/2021 17:00 (SGT)
Exact Location of Accident	Corporation Rd, Singapore
Additional Location Information	TOWARDS TAMAN JURONG.
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBJ5431E
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	SUN CHUAN CHAN SUPPLY & SERVICES
Company Reg No	53252078E
Email Address	darrenho140@hotmail.com
Mobile Phone No	(Phone) +65-96305716
Alternative Phone No	+65-96305716

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Dyna
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Manual
CC	2982

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	2070070860-01
Cover Note Number	-

DRIVER

Name of Driver	KOH CHEE LOO
NRIC No	S1761959D

Date Of Birth	28/07/1966
Occupation	Outdoor
Date Of Driving Pass	09/09/1986
Driving experience	34 YEARS AND 11 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96305716
Alt. Phone Number	-
Email Address	darrenho140@hotmail.com
Address	BLK 285 BUKIT BATOK EAST AVE 3
Address complement	#09-433
Postcode	650285
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	OWNER
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLS REFER TO THE POLICE REPORT:T/20210807/7031

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLG4539H
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car

Name of Driver -
 Contact Number -
 Address -
 Address complement -
 Postcode -
 Insurance Company Name -
 Nature Of Damage -
 Details of property damaged in accident -
 No. Of Passenger (Including Driver) -

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	KOH CHEE LOO
Gender	Male
Phone No	(Phone) +65-96305716
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	NECK & BACK
Injured person in which vehicle?	GBJ5431E
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

BUN CHUAN CHAN SUPPLY & SERVICES


John Chee too
Policyholder's Signature / Date & Time

John Chee too
Driver's Signature (If driver is not the policyholder) / Date & Time

lyn 12/05/21
Witnessed by Reporting Centre Personnel

Sketch Plan

CORPORATION ROAD TOWNSHIP JURONG



A: GBJ543IE

B: SLG4539H

Describe Circumstances of the Accident

ON THE STATED VENUE, DATE AND TIME, I VEHICLE A
 BEAR LORRY PLATE 4B35431E WAS TRAVELLING STRAIGHT IN MY
 LANE ON LANE 2. SUDDENLY I FELT A HUGE IMPACT FROM
 MY LEFT PORTION OF MY VEHICLE CAUSING ME TO RAMP UP
 THE KLIPB. I GET DOWN AND REALISE VEHICLE B BEARING
 (CAR PLATE SLA4539A) WAS THE ONE THAT COLLIDED ONTO
 ME.

Declaration

We declare the foregoing particulars are true in every respect.

SUN CHUAN CHAN SUPPLY & SONS

Koh Chee too Koh Chee too

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

12/08/21
 Witnessed by Reporting Centre Personnel



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20210807/7031

2 of 3

Report No. T/20210807/7031

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	KOH CHEE LOO	ID No.	S1761959D
Related Vehicle	GBJ5431E (Lorry)	Contact No.	96305716
Hospital/Clinic	NIL	Class of Driving Licence & Expiry	Class: 3 Date of Expiry: NIL
Date	07/08/2021	Date	07/08/2021
No. of Days granted Medical Leave	03	Degree of	Serious

Brief Details.

ON THE STATED VENUE, DATE AND TIME. I VEHICLE A BEARING LORRY PLATE (GBJ5431E) WAS TRAVELLING STRAIGHT IN MY LANE ON LANE 2. SUDDENLY I FELT A HUGE IMPACT FROM MY LEFT PORTION OF MY VEHICLE CAUSING ME TO RAMP UP THE KURB. I GET DOWN AND REALISED VEHICLE B BEARING CARPLATE (SLG4539H) WAS THE ONE THAT COLLUDED ON TO ME.

AFTER THE ACCIDENT I FELT PAIN ON MY NECK AND BACK SO I PROCEED TO KOVAN INTERMEDICAL TO CONSULT A DOCTOR AND RECEIVED 3 DAYS OF MC.