

FORM 100

ASS. REC. BY:

REF: CS3/

INC19015092/HK 03

Special Instruction:

Assigned: Hock Ann

Juliana Lee

ASSIGNMENT (Office)

11.03.2021

From (Person): Dante Lee

of

INC

Date/Time: 7:30am 27/10/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKX 168EC

Insured:

SKJ 4629C

at Workshop w/s

My car consultant

Tel:

8668832

at

53 ubi Ave 1 # 01-33

Policy No:

Claim No:

MP11059292-002

Sum Insured:

Excess:

Make of Veh:

D.O.A

22/8/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:22pm 27/10/19

Person Contacted:

Hui Qin

Vehicle IN: OUT

Date/Time	Action/Instruction	Estimated (X)
	SKX 168EC-X	
	SKJ 4629C-X	
	Disassemble: 30/8/2019	
	After repair: 2/9/2019	

ASS. REC. BY: H. Anu

REF:

INC

PRS

ASSIGNMENT

From:

Date:

29/8/19

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SKX 1688C

at Workshop mv's:

My Car Consultant

of

53 ubi Ave 1 #01-33

Insured:

Policy No.:

Claims No.:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

X	X
N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lim Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS^{up}

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKX 1688C

Yr Regn:

28/09/2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

H-vetel 1.5X HYBRID cc 1476

Colour:

B142

A/C:

Insured / Std / NI / NA

Sp. Reading:

068089 km

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

RM31178200

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 225/45/2R18

R:

225/45/2R18

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Fit and Rer same Brand

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

22/8/19

D.O.A.

22/8/19

Survey held at

my car consultant

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time:

Action / Instruction

repair days → 3 day

MV - 66.000

PV - 42.09K

NV - 21.900

range → 5-6.5K

* noted. This vehicle case
NON Estimate
(PRS) case &

mv - 66K

Date/Time, File Pass in?



Prel. Report

1)



Final Report

Date/Time, File Return in?

2)

Days Of Repair:

Resurvey No. of Trip:

2

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Insp (\$)



Weekend (\$)

Survey Fee:

Transportation:

E+PS \$

Photos

Others

TOTAL

\$50K

Report Format:

PRS

Lump Sum / H.B.J.: