REF: CS/EQ12/008416/4vf3
ASSIGNMENT

From: Date:	Veh No: 529/6005 Yr Regn: 29/11/16
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD /(TP) WS / TP RES / OD RES / EVA / INV / MV	Truck/Trailer or (A)
To Inspect Vehicle No: 52 J / 600 S	Make: Vo/vo 560 c.c /969
at Workshop m/s	Colour - Cory A/C: Insured / Std / NI / NA
of	Sp.Reading 93977 T/Radio: Insured / Std / NI / NA
Insured: 5MV 5-737E	Eng/No:
Policy No.	C/NO: YVIFSA8C DHZX26319
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil SARim / STD A/Rim or
(Policy Condition)	Tyre Size: F: 215-/5014) R:
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or Continute
Bal. or Market Value:	<u>Front</u> Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. / mm R/Bal. / mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. mm L/Bal. mm
Est. Repairs: 3 days Res.: Yes or No	D.O.A. 10 (8/2)
Lum Sum: 20 % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS  Vehicle: IN / OUT	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted: L1A 8 43823	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction Dor 1/K.  hereh 19  Conf. med L/S \$ 4000 W	0 01
8/11 Conf. mes 4/5 & 4000 W	the Men.
	× ·
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
1) : Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
Add Fee:	
	: Interview (\$ ) Photos
Report Format :	: Tech. Invs (\$ ) Others
Lump Sum / I.B.I: (\$	:Weekend (\$
	TOTAL

# submit to insurance

	FASTECH AUTO PTE LTD				
	1 Kaki Bukit Ave 6 #01-48 Autobay				
	Singapore 417883				
	Tel No: 67452063/67467158 Fax No :	67458520			
	Tax Reg No : 20006262D				
	VEHICLE No :SLJ 1600S				
1PC	REAR BUMPER	se/Torn	1750		\$1,800.00 /
1PC	REAR BUMPER BOTTOM	de	620		\$680.00
1PC	REAR BUMPER LOWER GARNISH	De	1 545		\$588.00
2PCS	REAR BUMPER PDC SENSORS @\$	225.00 Slub	191		\$450.00 (
ISET	REAR BUMPER CLIPS	ner	50		\$60.00
1PC	REAR BUMPER REINFORCEMENT	つう	815		\$1,210.00
IPC	REAR ANTENNA SENSOR	cre	915		\$298.00
PCS	REAR EXHAUST CHROMES @\$250	.00 R			\$500.00 📈
IPC	REAR EXHAUST HEAT SHIELD	1		(pro	\$269.00
IPC	REAR END PANEL	1		154	\$1,450.00
					\$7,305.00
	TO CHECK WIRING				\$50.00 2
	TO DISMANTLE & REPLACED REAR	PDC SENSOR			\$80.00 \$
	TO DISMANTLE & REFIX REAR GAR		,		↑↑ \$120.00 X
	TO SPRAY RUST PROOFING				\$50.00 X
	LABOUR FOR PANEL BEATING & RE	PLACED PARTS			\$800.00 4
	TO PUTTY & SPRAY PAINTING				\$900.00 50
				TOTAL	\$9,305.00

Not Authornal
Late
Late
3 July

LKK Auto Consultants hence notify

- the Repairer of the following: To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorised

7.4296 2-970 SY09218A000E / YEW TEE AUTOMOBILE TECH PTE LTD [737856]

ENTRY DATE & TIME: 10/08/2021 20:04 (SGT)

SUBMITTED BY: TOH TZE CHANG VERSION: 1 (10/08/2021 20:04 (SGT))



# SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
  3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

  5. Any false reporting may be referred to the Police for investigation.

  6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date of Submission 10/08/2021 20:04 (SGT) Date of Accident 10/08/2021 14:45 (SGT) Exact Location of Accident PIE, Singapore dditional Location Information PIE TOWARDS JURONG (BEFORE PAYA LEBAR EXIT) Country/State of Loss Singapore

### **DETAILS OF OWN VEHICLE**

SL.11600S

INSURED/POLICYHOLDER Is company? No Name Of Registered Owner
NRIC No MICHAEL CHONG CHEE KEONG SXXXX880I Email Address JASONKCAPL@GMAIL.COM Mobile Phone No (Phone) +65-82010557 Alternative Phone No (Home) +65-82010557

### VEHICLE PARTICULARS

Vehicle Registration Number

1anufacturer ..... Volvo Model S60 Variant ..... Exact purpose for which vehicle was being used at time of accident Private use Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party Vehicle Category Private car Transmission Manual CC 1969

#### INSURANCE COMPANY

Name of Insurance Company Liberty Insurance Pte Ltd Type of Coverage Comprehensive Fleet Policy Policy Number SI20V14385/VPE/R01 Cover Note Number

#### DRIVER

Name of Driver MICHAEL CHONG CHEE KEONG SXXXX880I

	Date Of Birth	15/05/1966
	Occupation	Indoor
	Date Of Driving Pass	21/01/1988
	Driving experience	33 YEARS AND 7 MONTHS
	Gender	Male
	Mobile Number	(Phone) +65-82010557
	Alt. Phone Number	(Home) +65-82010557
	Email Address	JASONKCAPL@GMAIL.COM
	Address	21 JALAN PACHELI
	Address complement	-
	Postcode	557359
	Is the driver the policyholder?	Yes
	If No, Relationship of the Driver with the Insured	-
	Does Driver Own Other Vehicles?	No
	Vehicle Registration Number of Other Vehicle Owned by Driver	110
	Insurance Company of Other Vehicle Owned by Driver	
	GENERAL INFORMATION OF THE ACCIDENT	
	The second secon	
	Tune of Assident	
	Type of Accident	Chain Collision
	Weather Conditions	Clear
-	Road Surface	Dry
	OTHER INFORMATION	
	Was any foreign vehicle involved in the accident?	No
	Number of vehicles involved in the accident	3
	Was anybody injured in the Accident?	Yes
	Was any injured conveyed to hospital by ambulance?	No
	Was any other vehicle or property damaged?	Yes
	Number of Passengers (Including Driver)	1
	Has the driver been approached by unknown person(s)	
	soliciting/offering accident claims assistance?	No
	DETAILS OF POLICE ACTION	
	Was the accident reported to the police?	No
	Was notice of intended Prosecution given?	No
	If yes, against whom?	140
	See Particular and Particular and Control	
45	CIRCUMSTANCES OF ACCIDENT	
	SINGS IN THE STATE OF A SHELLY	
	DEFED TO ATTACHMENT	
	REFER TO ATTACHMENT	
	ATTACHMENT(S)	
	Are accident photos available for attachment?	Yes
	Was there any video captured by Car Camera?	No
	Was there any audio recorded?	No
		Address:
	DETAILS OF OTHER	VEHICLE PROPERTY 1
	Vehicle Registration Number	SMV5737E
	Vehicle Manufacturer	OWY 0/0/L
	Vehicle Model	
	Vehicle Variant	
	Vehicle Colour	-
	Vehicle Category	Private car
	Name of Driver	-
	Contact Number	-

Address - Address complement -

Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	_
No. Of Passenger (Including Driver)	_

### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SNA9390T
Vehicle Manufacturer	-
Vehicle Model	_
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	_
Address complement	_
Postcode	_
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

## INJURED PERSONS DETAILS

#### INJURED 1

Name of injured person	MICHAEL CHONG CHEE KEONG
Gender	E.
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	2
Injured person in which vehicle?	SLJ1600S
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Flease report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Oriver.
- 3, adornation provided must be as truthful and accurate as possible. Any will discrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The assus and acceptance of this Fermby insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested purioe.
- 7. By the indgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made evalable aforesaid.
- 6. Consent under the Personal Data Protection Act (PDPA)

lunderstand, acknowledge, agree and consent that;

- (a) My Insurer , my workshop and the General heurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(a) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers have yearless firms, the Monetary Authority of Singapore and any interest. government agency/authority (such as the police), for the purpose(s) of ;
- (i) processing, handling end/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (ii) carrying out and/or dealing with my instructions or responding to any enquires by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vahicle(s) involved in this accident and the insurers' law year/law firms, maylere permitted in collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/ben be disclosed by any of the insurers and/or GPA to their third party service providers or agents (including their law yet allow Firms), which may be shed outside of Singapore, for one or more of the above Purposes.

Coloryholder's Signature / Date &	Physical Company of the Company of t	lai
IND	Driver's Signature (if driver is not the policyholder) / Date 8. Time	Wilnessed by Reporting Centre Personnel
ketch Plan		Pot sortiges
		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
712.17 (1 - 7 ) [6]		1 3 C 3 - 100
		the second second
	1 A	TO VMR IS INTERIOR
	2 1	A -QA-A -5121
		The second of the second
	1 - +   -   -   -   -   -   -   -   -   -	
1		
	· · · · · · · · · · · · · · · · · · ·	
111-14		
14 3		
		min e (manin) e final- a mel mi me

Dn 10/08/202	1 9+ 91	out 14	: 45PM	Was	travelly along	PIE herands
Jurong Before	Paya Le	bar Exit	E). [	Slowed	down due to	the
front vehicle Su	dolarly,	I felt a	n impa	ct from		restised
I was involved	in a 3	vehicles		collision	J	100
	***************************************					
	-					
		nucleus				
						200
				Margar at a		
			No. and Control of Con			
claration						
doctors the foregoing particula	rs are true in or	ery respect.				
f			11			


# > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	8801
Vehicle No.:	SLJ1600S
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Aug 2021
Vehicle Make:	VOLVO
Vehicle Model:	S60 D4
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	D4204T141758954
Chassis No.:	YV1FSA8CDH2426319
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$27,841.00
Original Registration Date:	29 Nov 2016
First Registration Date:	29 Nov 2016
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$20,978.00 10489
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Nov 2026
PARF Rebate Amount: Intended COE Rebate Details	\$15,733.00
COE Expiry Date:	28 Nov 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,001.00
COE Rebate Amount:	\$28,090.00
Total Rebate Amount:	\$43,823.00

#### SGCARMART.COM

Login Sign up **New Cars** Used Cars Rental Cars Sell My Car Directory Products Articles 2011 BMW 730Li @ 138888 Post an Advertisement **PRIME MOTOR & LEASING** Sell it yourself! Advertise it at just Underutilized, Immaculate \$68 until it's SOLD! With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes. Direct Owner StarAd Post an Ad Advertiser Login Ways of Selling





12 Months Warranty! Attractive Financing Rates And In House Loan Available! Gorgeous Grey Paintwork With Black Leather Interior! Co.. PREMIUM AD Supreme Cars Pte Ltd

Posted: 06-Aug-2021 Tags: 2016 Volvo S60, Volvo S60, Volvo, S60



Gary's Engineering Pte Ltd - Specialist for Volvo Car repair, servicing & maintenance Gary's Engineering specialises in doing comprehensive servicing and professional tuning for better performances and fuel saving. More info about this shop



\$83,700 \$13,450 /yr 26-Oct-2016 1,498 cc 59,154 km Luxury Available COE Dropped! Our Price Dropped Too! Rare 1 Owner With Low Mileage Done. Comes With Nice Auspicious Bidded Number Plate. 100%..

AutoPrestige Gallery Pte Ltd Posted: 06-Aug-2021 Tags: 2016 Volvo S60, Volvo S60, Volvo, S60



Volvo S60 T5 \$65,800 \$11,660 /yr 22-Jan-2016 1,969 cc 71,300 km Luxury Available Graded B by STR

Volvo S60 T2

Low Mileage, 1 Owner Only. Clean And Neat Interior, Well Maintained By Previous Owner! Buy With A Peace Of Mind From Award Accre... PREMIUM AD Autolink Holdings Pte Ltd

Posted: 06-Aug-2021 Tags: 2016 Volvo S60, Volvo S60, Volvo, S60



2 Owner. Agent Unit (Wearnes Automotive). Accident Free. Reguarly Serviced, Flawless Interior/Exterior Condition. Very Clean & Neat In...

26-Feb-2016

1,498 cc

103,800 km

Luxury

\$10,260 /yr

Posted: 31-Jul-2021 Tags: 2016 Volvo S60, Volvo S60, Volvo, S60

\$59,800

Available