



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC20012184/Gtf3e2-1 Date: 07/09/2021 Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBE 5117P	Veh. Inspected	SLW 9181M	
Policy No.		Coverage (\$)	0.00	
Claim No.	19/20/20/VP05/023861	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	11/08/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA VEZEL 1.5X	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	RU11231990	Colour	WHITE	
Odometer	66107 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	6 mm	
L/H Front Tyre	215/60 R16	DUNLOP	6 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	05/11/2020	Inspection Date	08/11/2020	
Survey held at	EDWIN GARAGE 5032 ANG MO KIO INDUSTRIAL PARK 2 #01-295 ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569535			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	