

LI07/9/67
ASS. REC. BY: Tauji

REF:


004/FCI/21008454/Tira3

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD/TP/WS/TP RES/OD RES/EVA/INV/MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: \$56K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Darren

Vehicle: IN / OUT

Veh No: SMK 7280A Yr Regn: 20.9, Apr 1
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Mitsubishi Atrage c.c. 1193
Colour: Silver A/C: Insured / Std / NI / NA
Sp. Reading: 106631 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: MMB5TA13AKH001400
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modl: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 185/55R15
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Giti
Front: _____ Rear: _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 12/8/21 2200pm
Survey held at Teamwork
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Fv70/s, 4/c
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / L.B.A. /

Unconfirm

1

LOWER ARM (REAR RIGHT)

Submit

Save

Add Fee:

☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

____ \$ + RS ____ \$

Photos

Others

TOTAL

FCI

Vehicle number	SMK7280A
Make / Model	MITSUBISHI ATTRAGE
Chassis number	MMBSTA13AKH001400
Accident date	9/8/2021
Reference	2108-04

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT BUMPER	687.20 <i>del</i>
2	FRONT BUMPER RETAINER	<i>LHX</i> 56.40 <i>Ry new</i>
1	FRONT BUMPER FOG LAMP	189.60 ?
1	FRONT BUMPER FOG LAMP COVER	89.20 <i>cut</i>
1	FRONT BUMPER FOG LAMP CHROME	138.50 <i>cut</i>
1	FRONT BUMPER INNER GARNISH	186.65 ?
1	FRONT BUMPER REINFORCEMENT	387.90 ?
1	FRONT BUMPER LOWER GRILLE	168.00 ?
1	FRONT GRILLE	322.80 X
1	FRONT GRILLE OUTER CHROME MOULDING	246.60 X
1	FRONT GRILLE EMLBEM	87.00 X
1	FRONT FENDER RH	438.90 <i>bl</i>
1	FRONT FENDER INNER SHIELD RH	181.40 ?
1	FRONT FENDER EMBLEM	59.00 <i>new</i>
1	FRONT FENDER INNER PANEL	469.90 X
1	FRONT FENDER BRACKET RH	52.25 ?
1	WASHER TANK	89.20 ?
1	HEADLAMP RH	576.00 <i>cut</i>
1	BONNET	722.00 <i>Ry</i>
2	BONNET HINGE	183.00 X
1	FRONT LOWER ARM RH	268.00 <i>*?</i>
1	FRONT SHOCK ABSORBER RH	344.70 X
1	FRONT KNUCKLE ARM RH	438.00 X
1	FRONT KNUCKLE ARM BEARING RH	389.60 <i>*?</i>
		6771.80
Less 10%		677.18
Subtotal		6094.62
Balance C/F		
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1 SET	FRONT BUMPER CLIP	30.00 <i>new</i>
1 SET	FRONT FENDER INNER SHIELD CLIP	30.00 <i>20 10</i>
1	BRAKE FLUID	50.00 X
1	FRONT TYRE	250.00 X
1	FRONT RIM	400.00 <i>cut</i>
Subtotal		760.00

S/No	LABOUR AND MISCELLANEOUS CHARGES	
1	CHECK FRONT WIRING AND LIGHTNING SYSTEM	60.00 30
2	COMPUTERISED AND CHECK WHEEL ALIGNMENT	200.00 80
3	REMOVE AND REPLACE FRONT UNDERCARRIAGE	200.00 100?
7	PANEL BEATING ON AFFECTED AREAS	1200.00 400
8	SPRAY PAINTING ON AFFECTED AREAS	1200.00 500
9	APPLY ANTI RUST ON AFFECTED AREAS	150.00 30
	Subtotal	3010.00
	Grand total	9864.62

Tanphir 97495749
 'up' 12/6/21 @ 220 pm
 1/3 Resurvey after repair
 Tanphir @ 1/16/2021
 4 days

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: