



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: NG STACEY			Ref: CS/ASM21008456/Guce2 Date: 07/12/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 9786R	Veh. Inspected	SMA 7211C
	Policy No.	VFX/P2413997	Coverage (\$)	0.00
	Claim No.	S1M03FEU	Excess (\$)	0.00
	Assign From	NG STACEY	Assign Date	12/08/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA C-HR	c.c	1797
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	ZYX102112281	Colour	GREY
	Odometer	316643 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R17	YOKOHAMA	6 mm
	L/H Front Tyre	215/60 R17	YOKOHAMA	6 mm
	R/H Rear Tyre	215/60 R17	YOKOHAMA	6 mm
	L/H Rear Tyre	215/60 R17	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	07/08/2021	Inspection Date	25/08/2021
	Survey held at	OOHRAI RENTAL PTE LTD 8 KAKI BUKIT AVENUE 4, #06-31, PREMIER @ KAKI BUKIT, SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	