

ASS. REC. BY: Tang JH

REF: 03/FC/21/008453/1, WS

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: **SBS 6492A**

Policy No. \_\_\_\_\_

Claims No. **D21002293MFBP**

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SBS3928E Yr Regn: 20151 Mult

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: W/vo. L9TL c.c. 9364

Colour: Mult A/C: Insured / Std / NI / NA

Sp. Reading: 488061 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_ C/No: 9V 354P 926 FR / 70650

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_

Brake: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_

Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_

Tyre Size: F: 275/70R22.5 R: u(D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 8 mm R/Bal. 8/8 mm

L/Bal. 8 mm L/Bal. 8/8 mm

D.O.A. 9/8/21 D.O.I. 13/8/21 0330pm

Survey held at SBS Bedok Depot

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
23/9/21	Submit \$1989 (Red 0)

Date/Time, File Pass to?  : Preli. Report  
 : Final Report

1) \_\_\_\_\_  
Date/Time, File Return to?  
2) 23/9/21-typist

Rep. Format: TP  
Lump Sum / L.B.H. (\$ 1989)

Days Of Repair: 3  
Resurvey No. of Trip: 1

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Invs (\$ \_\_\_\_\_)  
 : Weekend (\$ \_\_\_\_\_)

Survey Fee:	100
Transportation:	50
____S + RS____SI	50
Photos	26
Others	
TOTAL	226