



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21008460/Atf3n2	
			Date: 18/10/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBH 7705M	Veh. Inspected	GBB 8193P
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2102386/GPL	Excess (\$)	0.00
	Assign From	MELVIN YE YONG KANG	Assign Date	12/08/2021
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN NV200	c.c	1461
	Engine No.	HIDDEN	Year of Reg.	2010
	Chassis No.	JN1YBAM20U0002849	Colour	WHITE
	Odometer	177071 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/70 R14	YOKOHAMA	6 mm
	L/H Front Tyre	185/70 R14	YOKOHAMA	6 mm
	R/H Rear Tyre	185/70 R14	YOKOHAMA	6 mm
	L/H Rear Tyre	185/70 R14	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	11/08/2021	Inspection Date	13/08/2021
	Survey held at	GLOCKEWERKE 21 KAKI BUKIT ROAD 4 #01-02 SYNERGY @ KB SINGAPORE 417810		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	