

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AXA INSURANCE I	PTE LTD		Ref:	CC4/ASM21008469/Tpa3q2	
	8 SHENTON WAY AXA TOWERSING			Date:	26/07/2022	
	ATTN:CYNTHIA			Code:	ASM	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SHD 3247U	Veh. Inspected	l	SKT 1615J	
	Policy No.	P2419138	Coverage (\$)		0.00	
	Claim No.	S1M03FFH	Excess (\$)		0.00	
	Assign From		Assign Date		12/08/2021	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA WISH	c.c		1987	
	Engine No.	HIDDEN	Year of Reg.		2009	
	Chassis No.	JTDGJ20W005001454	Colour		BLUE	
	Odometer	195354 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	215/45 R17	DUNLOP		6 mm	
	L/H Front Tyre	215/45 R17	DUNLOP		6 mm	
	R/H Rear Tyre	215/45 R17	DUNLOP		6 mm	
	L/H Rear Tyre	215/45 R17	DUNLOP		6 mm	
4.	. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	10/08/2021	Inspection Dat	е	12/08/2021	
	Survey held at	AP AUTOMOTIVE SERVICES P	TE LTD			
		9006 TAMPINES ST 93 #01-202 TAMPINES INDUSTRIAL PARK A SINGAPORE 528840				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	STIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					