SYOA217L0002 / YEW TEE AUTOMOBILE TECH PTE LTD [417800] ENTRY DATE & TIME: 21/07/2021 16:41 (SGT) SUBMITTED BY: TOH LEI MING VERSION: 1 (21/07/2021 16:41 (SGT))



# SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be <u>completed by the Policyholder and/or the Authorised Driver</u>
   Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies,

- 5. Any fake reporting may be referred to the Police for Investigation.
  6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## **ACCIDENT STATEMENT**

Date of Submission Date of Accident Exact Location of Accident Additional Location Information Country/State of Loss

21/07/2021 16:41 (SGT) 20/07/2021 14:16 (SGT) 115 Marsiling Rise, Block 115, Singapore 730115 CARPARK NO.WLW18 Singapore

## **DETAILS OF OWN VEHICLE**

Vehicle Registration Number

SLQ5095L

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner

Company Reg No **Email Address** Mobile Phone No

Alternative Phone No

Yes

MOVESAFE 5XXXX720D

XINHUAWORKSHOP@GMAIL.COM

(Phone) +65-96261886 (Home) +65-96261886

VEHICLE PARTICULARS

Manufacturer

Model Variant

Exact purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category Transmission

CC

Kia Niro

Private hire

No - Claiming third party

Private hire Auto 0

INSURANCE COMPANY

Name of Insurance Company

Type of Coverage Fleet Policy Policy Number Cover Note Number

DRIVER

Name of Driver NRIC No

NTUC Income Insurance Co-operative Ltd

Comprehensive

No

5102090616-03

POO KA SUN SXXXX029G

Date Of Birth Occupation

Date Of Driving Pass Driving experience

Gender

Mobile Number

Alt. Phone Number Email Address

Address

Address securis

Address complement

Postcode Is the driver the policyholder?

If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident

Weather Conditions Road Surface

OTHER INFORMATION

Was any foreign vehicle involved in the accident?

Number of vehicles involved in the accident Was anybody injured in the Accident?

Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged?

Number of Passengers (Including Driver)
Has the driver been approached by unknown person(s)

soliciting/offering accident claims assistance?

DETAILS OF POLICE ACTION

Was the accident reported to the police?

Was notice of intended Prosecution given?

If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHED

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera?

Reasons for not uploading a video of the accident

Was there any audio recorded?

Yes

19/08/1971

13/03/2008

13 YEARS AND 4 MONTHS

XINHUAWORKSHOP@GMAIL.COM

APT BLK 447 JURONG WEST ST 42 #09-296

(Phone) +65-96261886

Collision - Head to Rear

Outdoor

Male

640447

**OWNER** 

Nο

No

Clear

Dry

No

No

Yes

No

No

No

2

Yes

WITH OWNER

No

**DETAILS OF OTHER VEHICLE PROPERTY 1** 

Vehicle Registration Number

Vehicle Manufacturer Vehicle Model

Vehicle Variant

Vehicle Colour

Vehicle Category

Name of Driver

Contact Number

Address

GBB6971Z

-

\_

Commercial vehicle

-

-

-

Accident report SY0A217L0002

Page 2 of 15

Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any willul misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Formby insurance companies is not an admission of policy fability on the part of the insurance companies
- 5. Any false reporting may be referred to the Police for investigation
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) styleted in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers 'lawyers/law trims, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (F) investigating the accident and/or my claims;
- (ii) carrying out and/or dealing with my instructions or responding to any enquries by me;
- (b) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of cortain personal data about me to bring about delivery of the same as welf as on the external cover of envelopes/mail packages), and/or

(collectively the 'Purposes')

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers law yersilaw firms, may are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

CO VE SO THE

Policyholder's Signature / Date &

Children

Oriver's Signature (If driver is not the policy

Driver's Signature (If driver is not the policyholder) / Date

Witnessed by Repaying Centre Personnel

Sketch Plan

BIK 115 Mors ling Rise

The Stationers

A

A

A

A=SLQ5095L

3=6BB6971Z

BIK 115 Marsiling Rise

(Car palk NO WLW18)

Describe Circumstances of the Accident
<u> </u>
Refer to attached
/
The state of the s
/

## Declaration

iWe declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

On 20.07.21 at about 14:16 hours at Blk 115 Marsiling Rise (Car park No: WLW18) . While I was travelling on my lane to fetch my Grab passenger.

Suddenly I saw my front vehicle (B) reversing, I immediately apply my horn to alert the vehicle (B) driver. Unfortunately he still keep on reversing and hence collided into my front portion of my vehicle (A) causing damages to my vehicle.

Simon

Vehicle (A): SLQ5095L

Vehicle (B): GBB6971Z

