

XIN HUA WORKSHOP PTE. LTD.

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933

Reg : 201838521G

Vehicle Number : GBD410E
 Vehicle Model : TOYOTA HIACE
 Accident Date : 27.07.2021
 Original Reg Date : 06.05.2014

TP China
 Cecilia

Date : 11.08.2021
 Chassis : JTFHT02P100138125
 TP Ins. CHINA TAIPING

ESTIMATE

1	1 pc	Front bonnet <i>Dented</i>		698.70	
2	2 pc	Front bonnet hinges <i>new</i>	65.20	130.40	
3	1 pc	Front bonnet logo <i>new</i>		95.20	
4	1 pc	Front bonnet inner lock <i>new</i>		298.60	
5	1 pc	Front corner panel <i>Buckled</i>		198.20	
6	1 pc	Front Bumper <i>Dented</i>		598.20	
7	1 pc	Front Bumper grille base <i>cracked</i>		526.90	
8	1 pc	Front Bumper grille top garnish <i>cracked</i>		345.80	
9	1 pc	Front Bumper grille lower garnish <i>cracked</i>		259.60	
10	1 set	Front Bumper grille clips <i>new</i>		30.00	
11	1 pc	Front Bumper foglamp grille Lh <i>Dented</i>		98.60	
12	1 pc	Front Bumper Side Retainers <i>new</i>		145.80	
13	1 pc	Front Bumper Reinforcement <i>new</i>		458.20	
14	1 set	Front Bumper Clips <i>new</i>		50.00	
15	1 pc	Front Bumper Top Beam <i>new</i>		379.80	
16	2 pcs	Front Bumper Reinforcement Side Bracket <i>new</i>	138.00	276.00	
17	1 pc	Headlamps <i>cracked</i>		798.50	
18	1 set	Headlamps clips <i>new</i>	30.00	60.00	
19	1 pc	Front washer tank <i>new</i>		158.20	
20	1 pc	Front wiper garnish <i>new</i>		185.20	
21	1 pc	Front door <i>Repair</i>		1,785.20	
22	1 pc	Front step panel garnish <i>new</i>		145.80	

subtotal 7,722.90
 Less 25% 1,930.73
 total **5,792.18**

3774.70

25831602

Special Nett

1	1 set	Front door company sticker <i>xlw</i>		35.00	<i>30</i>
2	1 pc	Front Number Plate <i>nlw</i>		50.00	<i>+</i>
3	1 set	Radiator Coolant <i>nlw</i>		60.00	<i>+</i>

Labour charge

Panel Beating, to weld and align damaged parts		1,200.00	<i>400</i>
Spray painting		1,200.00	<i>550</i>
Check Wiring on headlamp		120.00	<i>30</i>
Anti rust		120.00	<i>40</i>

Total **8,577.18**

Adrian Li
L/S 11/08/21.

04 Days.

total: 3881.02

L/S: 3.1K

3.1K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: