

# COMFORTDELGRO ENGINEERING

Our Job Ref No 305482029  
Date : 13/08/2021

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK  
Attn : THEVAN  
: SH 6456L

Fax :

DOA: 09/08/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- SML2224R  
###
2. The finalized amount shall be:
 

(a) Spare Parts after List discount	<u>\$1,981.24</u>
(b) Labour Charges	<u>\$630.00</u>
<b>Total for Part-By-Part Repair Cost</b>	<b><u>\$2,611.24</u></b>
- (c) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: 20%  
**Final Lumpsum Repair cost**

3. Estimated normal period for repairs: 2 working days
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : [Signature]  
Name : JUMANI  
Tel : 6214 8315  
Fax : 65468156

Signature : [Signature]  
Name : Thevan  
Date : 13/8/21

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	NO		
3. Survey Fees	---			
4. LTA Search Fee	\$7.49 - \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD  
REPAIR ESTIMATE

Date: 12.08.2021  
Time: 15:18:40  
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305482029  
REGN NO : SH 6456L  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : IONIQ(G3)  
DATE OF REGN : 29.04.2021  
DATE/TIME IN : 10.08.2021 09:45  
ACCIDENT DATE : 09.08.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-0578-G COVER-FR BUMPER#	1	460.90	20.00	368.72	✓cut
0002 04-01-0104-2835-G LAMP ASSY-HEAD LH#	1	1,993.65	20.00	1,594.92	✓cra
0003 04-01-0101-0111-G BUMPER COVER CLIP	10 L	22.00	20.00	17.60	✓nec
SUB-TOTAL :					1,981.24 ✓

JOB NATURE

0000 PB	PANEL BEATING	350.00	✓
0001 SP	SPRAYPAINT CHARGE	250.00	✓
0002 17-01	CHECK ALL LIGHTING	30.00	✓
SUB-TOTAL :		630.00	✓

TOTAL : 2,611.24 ✓

Jumani  
MVA NAME & SIGNATURE  
DATE :

Thuan  
SURVEYOR NAME & SIGNATURE  
DATE : 13/8/21  
AUTHORISED : YES / NO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: