

COMFORTDELGRO

ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Our Job Ref No : 305482216
Date : 13/08/21

FINALIZATION FORM

To : LKK


Fax :

Attn : TAUFIKH

Vehicle Reg No. : SHA 88Y

Date of Accident : 09/08/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- SJV1263S
 2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$1,591.06
 - (b) Labour Charges \$630.00
 - Total for Part-By-Part Repair Cost** \$2,221.06
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost
 3. Estimated normal period for repairs: 2 working days.
 4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
 5. Thank you for your assistance. We confirm the estimates and finalized amount
- Signature :  Signature : 
Name : LIM T S Name : TAUFIKH
Tel : 62148398 Date : 16/8/21
Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	\$7.49 /\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

[illegible]

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010070
 ADDRESS : CITYCAB PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65551188

JOB NO : 305482216
 REGN NO : SHA 88Y
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 22.10.2019
 DATE/TIME IN : 10.08.2021 15:20
 ACCIDENT DATE : 09.08.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	28-01-0104-2029-A	REAR NO.PLATE W/TRIM CVR	1	55.00	10.00	49.50
0002	04-01-0104-2533-G	REAR BUMPER CTR MOULDING	1	451.25	20.00	361.00
0003	04-01-0104-2545-G	REAR BUMPER LWR MOULDING	1	155.00	20.00	124.00
0004	04-01-0101-0111-G	REAR BUMPER CLIPS	10	22.00	20.00	17.60
0005	09-01-9999-0068-A	REVERSE SENSOR	1	180.00	10.00	162.00
0006	04-01-0104-2282-G	REAR BUMPER	1	459.40	20.00	367.52
0007	04-01-0104-2288-G	REAR BUMPER REINFORCEMENT	1	394.80	20.00	315.84
0008	09-01-0104-2133-G	REAR SMART KEY ANTENNA***	1	40.50	20.00	32.40
0009	04-01-0104-2370-G	REAR BUMPER FOGLAMP	1	201.50	20.00	161.20

SUB-TOTAL : 1,591.06

JOB NATURE

0000	PB	PANEL BEATING-SHA 88Y	350.00
0001	SP	SPRAYPAINT CHARGE	250.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305482216
REGN NO : SHA 88Y
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 22.10.2019
DATE/TIME IN : 10.08.2021 15:2
ACCIDENT DATE : 09.08.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0002 L R/I REVERSE SENSORS 30.00

SUB-TOTAL : 630.00

TOTAL : 2,221.06


MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO