

Our Job Ref No : 305482027  
Date : 14/08/21

## COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156


### FINALIZATION FORM

To : LKK Fax :  
Attn : Mr TAUFIKH  
Vehicle Reg No. : SHC1802K CTPL 07/08/2021

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- The repair job shall bill to: NTUC --- SCJ8386X
- The finalized amount shall be:
  - Spare Parts after List discount
  - Labour Charges
  - Total for Part-By-Part Repair Cost**
  - Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: 20%  
**Final Lumpsum Repair cost** \$1,800.00
- Estimated normal period for repairs: 2 working days.
- We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
- Thank you for your assistance.

We confirm the estimates and  
finalized amount

Signature :   
Name : MS. LOKE YY  
Tel : 62148355  
Fax : 65468156

Signature : taufikh  
Name : Taufikh  
Date : 30/8/21

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

VEHICLE I: SHC1802K

NTUC

305482027

TYPE OF C: TP

SURVEY B: LKK/TAUFIKH

DATE : 14/08/2021

## SUPPLEMENTARY OF PARTS AND LABOUR COSTS

DESCRIPTION	QTY	ESTIMATE	\$	REMARKS
RR BUMPER UNDER COVER CENTRE	1	mis ✓	\$225.00	MISSING
		TOTAL	\$225.00	