

REF: CS/LAW21008499/Uuf3

Special Instruction:

L/SUM : \$ 24,000.00

Third Parties:

Claimant:

Surveyor:

Workshop: HENG MOTOR SERVICES

ASSIGNMENT (Office)

From (Person): TEO WENG KIE of LAW Date/Time: 2/8/2021 9:24 PM
 Estimated Cost: _____ Bill to: _____

OD TP Re-inspection Evaluation

To Inspect Vehicle No: SMP 1911B Insured: SHC 6191G

at Workshop m/s HENG MOTOR SERVICES Tel: 8112 3936

of NO. 91 DEFU LANE 10 #01-05A SWEE HIN BUILDING

Policy No: BK.19771.20.P

Claim No: (V)TWK/DAQ/pkf/0522.21

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 17/2/2020
(Client's Record)

(Client's Record) 01-09-21-10a.m-12p.m

H.O.D. Endorsement/Date: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: 18/10/2021 Confirmed with _____ Final Fig _____, ____ days (Red \$ ____/____%; Original ____ days)

Date/Time: 18/10/2021 Submit Final Fig \$15000, 5 days (Red \$9000 / 38%; Original 7 days)

[illegible]

Para(1) : Parts found not replaced (To highlight *R* or *UB*, *LR*, *Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value : _____

Salvage Value : _____

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Basic & Add

Transport

Photos

Others

Total

Date: _____

1) Date/Time _____ File Pass to _____

2) Date/Time _____ File Return to _____

3) Date/Time _____ File Pass to _____

4) Date/Time _____ File Return to _____

5) Date/Time _____ File Pass to _____

6) Date/Time _____ File Return to _____