

ASS. REC. BY:

REF:

MSG/ 21008505/KV

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

4-5 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMN 31406

Yr Regn:

07/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Siento

c.c

1496

Colour

White

A/C:

Insured / Std / NI / NA

Sp. Reading

17300

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MHF 22814 35000 64849

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / RIM or

Tyre Size:

F:

195/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

11/8/21

D.O.I.

17/8/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

ump Sum / I.B.I: (\$

JA AUTOCARE PTE LTD

Blk 24 #03-35
Sin Ming Road
Singapore 570024
Tel : 94513429

Not Authorized
1/Rep &
Pruning After Painting
4-5 days

ESTIMATE

MSIG Insurance (Singapore) Pte Ltd
16 Raffles Quay
#24-01 Hong Leong Building
Singapore 048581
Attn: Motor Claims Department

Date: 13.08.2021
Vehicle no: SMN 1348G31406 *Tr*
Model: TOYOTA SIENTA
DOA: 11.08.2021

PARTS

- 01) Rear bumper
- 02) Rear bumper clips
- 03) Rear bumper bracket @\$60.00 x2
- 04) Rear bumper retainer @\$50.00 x 2
- 05) Rear Bumper centre pad
- 06) Rear Bumper centre pad reflector rh
- 07) Rear bumper centre reflector
- 08) Reverse sensor Socket
- 09) Rear panel outer
- 10) Tail gate
- 11) Tail gate rubber
- 12) Tail gate centre chrome
- 13) Tail gate lock
- 14) Tail gate inner trim board
- 15) Tail gate inner trim board clips
- 16) Toyota logo
- 17) SIENTA emblem
- 18) Tail lamp assy rh
- 19) Rear wiper motor assy

\$	<i>Buc 100</i>	650.80	✓
\$	<i>Re</i>	80.00	✓
\$	<i>X</i>	120.00	X
\$	<i>in</i>	100.00	✓
\$	<i>Re</i>	350.80	✓
\$	<i>Re</i>	120.50	✓
\$	<i>in</i>	85.50	X
\$		350.80	✓
\$		350.00	✓
\$	<i>Re</i>	1,450.80	✓
\$	<i>Dis 100</i>	250.80	50
\$	<i>in</i>	320.50	X
\$	<i>Re</i>	330.50	✓
\$	<i>in</i>	380.00	X
\$	<i>nn</i>	60.00	X
\$	<i>Re</i>	85.00	✓
\$	<i>Re</i>	95.00	✓
\$	<i>in</i>	550.80	X
\$	<i>in</i>	980.50	X
\$		6,712.30	
Less 25%	\$	(1,678.07)	
	\$	5,034.23	

S/Nett

- 20) Rear windscreen sealant and clip
- 21) Reverse sensor

\$	<i>Re</i>	100.00	60
\$	<i>Re</i>	380.00	20
\$		480.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JA AUTOCARE PTE LTD

Blk 24 #03-35

Sin Ming Road

Singapore 570024

Tel : 94513429


ESTIMATE

MSIG Insurance (Singapore) Pte Ltd
16 Raffles Quay
#24-01 Hong Leong Building
Singapore 048581
Attn: Motor Claims Department

Date 13.08.2021
Vehicle no : SMN 1346G31406
Model: TOYOTA SIENTA
DOA : 11.08.2021

Labour charges

22) To dismantle upholstery	\$	150.00	60h
23) To check wiring	\$	120.00	20h
24) to apply anti rust chemical	\$	140.00	7
25) To dismantle rear windscreen glass	\$	140.00	120h
26) To knock out dent on affected areas and renew parts	\$	1,200.00	?
27) To putty & respray painting	\$	1,200.00	60h
	\$	<u>2,950.00</u>	
Sub Total	\$	8,464.23	


for JA AUTOCARE PTE LTD

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 12/08/2021 15:12 (SGT)
Date of Accident 11/08/2021 09:00 (SGT)
Exact Location of Accident Singapore
Additional Location Information ALONG THIMSON ROAD TOWARDS NOVENA
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMN3140G
INSURED/POLICYHOLDER
Is company? No
Name Of Registered Owner PHANG CHUN YANG
NRIC No SXXXX128G
Email Address Pcy5287@gmail.com
Mobile Phone No (Phone) +65-96158987
Alternative Phone No +65-96158987

VEHICLE PARTICULARS

Manufacturer Toyota
Model Sienta
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1496

INSURANCE COMPANY

Name of Insurance Company Aviva Ltd
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 10996971
Cover Note Number NA

DRIVER

Name of Driver KONG HUI SHAN, JANICE
NRIC No SXXXX038A

Accident report SA0A218C0001

x family

CONTACT POINT

K A K B

AB LMN3140G.

BUS LANE

B: SLJ1849S.

THOMSON ROAD TO NOVEVA.

VERIFIED BY AJAX MARS (ARC)
REPORTING OFFICER
HASHIM BIN KAMARI

Policyholder's Signature
Date & Time:

x family

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PIA No.: