

(08/11/13) wef

ASS. REC. BY: *Passer*

REF:

C66/CT121008.533/R1ea3

502A

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SKF 222ST*at Workshop m/s *Automotive Repair CTR*  
of *68, POK GUNAN RD EAST #02-146/147*  
Insured: *CTR*

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: *57K*

IDAC Accident Rport:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

*SKF 222ST*

Yr Regn:

*2016 / MAY*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

*Honda Vezel 1.5 XA*C.C. *1496*

Colour:

*Grey*

A/C: Insured / Std / NI / NA

Sp. Reading

*141655*

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

*Ruj111 5708*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

*215/60R16*

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal.

*6*

mm

R/Bal.

*6*

mm

L/Bal.

*6*

mm

L/Bal.

*6*

mm

D.O.A.

*13/08/21*

D.O.I.

*16/08/21*

Survey held at

*ARC*Des. of Damages: Frt / *Rear* / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

*Repair limit - 28K*

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) S + RS, SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

**Estimate**

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2108-163 TG

DATE : 13-Aug-2021

POLICY NO. : FWD PNPV2017-00003264-04

VEHICLE REG. NO. : SKF2225T

VEHICLE MAKE : HONDA VEZEL 1.5X A

TO Motor Claim Department  
 China Taiping Insurance (Singapore) Pte. Ltd  
 3 Anson Road, #15-00 Springleaf Tower  
 Singapore 079909  
 Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

**ESTIMATE REPAIR COST**

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
<b>SPARE PARTS</b>				
1	Rear Bumper <i>De ✓</i>	1	\$ 880.00	\$ 880.00
2	Rear Bumper Clip <i>De ✓</i>	10	\$ 5.00	\$ 50.00
3	Rear Bumper Retainer RH <i>X</i>	1	\$ 35.00	\$ 35.00
4	Rear Bumper Retainer LH <i>X</i>	1	\$ 35.00	\$ 35.00
5	Rear Bumper Reflector RH <i>X</i>	1	\$ 150.00	\$ 150.00
6	Rear Bumper Reflector LH <i>X</i>	1	\$ 150.00	\$ 150.00
7	Tailgate <i>bt ✓</i>	1	\$ 1,080.00	\$ 1,080.00
8	Tailgate Lock <i>f</i>	1	\$ 280.00	\$ 280.00
9	Tailgate Rubber Seal <i>De ✓</i>	1	\$ 120.00	\$ 120.00
10	Rear Vezel Emblem <i>De ✓</i>	1	\$ 80.00	\$ 80.00
11	Rear Honda Emblem <i>X</i>	1	\$ 80.00	\$ 80.00
12	Rear Spare Tire Board Cover <i>X</i>	1	\$ 350.00	\$ 350.00
13	Rear Tools Sponge Box/Tray <i>X</i>	1	\$ 250.00	\$ 250.00
14	End Panel Top Garnish <i>X</i>	1	\$ 200.00	\$ 200.00
15	End Panel <i>Repair ✓</i>	1	\$ 480.00	\$ 480.00
16	Rear Buzzer <i>3X</i>	2	\$ 110.00	\$ 220.00
Total Spare Parts				\$ 4,440.00
<b>SPECIAL NETT</b>				
17	<i>License Plate &amp; Carving</i>	1	<i>40</i>	\$ 40.00 <i>35</i>
18	Reverse Sensor	2	\$ 200.00	\$ 400.00 <i>200?</i>
Total Special Nett				\$ 400.00
<b>LABOUR</b>				
19	Spray Painting Rear Bumper, Tailgate & End Panel	1	\$ 900.00	\$ 900.00 <i>500</i>
20	Replace Rear including Fitting, Cut, Weld and Re-align	1	\$ 900.00	\$ 900.00 <i>500</i>
21	Remove and Refit Rear Bumper Reverse Sensor	1	\$ 80.00	\$ 80.00 <i>60</i>
22	Repair, Replace and Refit Affected Accident Area	1	\$ 80.00	\$ 80.00 <i>X</i>
23	Transfer Tailgate Fitting & Window Mechanism to New Tailgate	1	\$ 80.00	\$ 80.00 <i>60</i>
24	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00 <i>40</i>
25	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00 <i>X</i>
Total Labour				\$ 2,170.00
Amount Before Excess				\$ 7,010.00

Estimate prepared by: Ken Ho

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started.





# Automotive Repair Centre Pte Ltd

CO. Reg. No. : 201312913C  
GST Reg. No. : 201312913C

## Estimate

38 Woodlands Industrial Park E1  
#05-18, Singapore 757700  
Tel: 64688834 Fax: 64622278  
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2108-163 TG  
DATE : 13-Aug-2021  
POLICY NO. : FWD PNPV2017-00003264-04  
VEHICLE REG. NO. : SKF2225T  
VEHICLE MAKE : HONDA VEZEL 1.5X A

TO Motor Claim Department  
China Taiping Insurance (Singapore) Pte. Ltd  
3 Anson Road, #15-00 Springleaf Tower  
Singapore 079909  
Tel: 6389 6116, Fax: 6222 1033

### FOR SURVEYOR

Resue - Hy 900 10068  
5 days / Lump sum  
18/08/12 @ 1010 / Resue after repair

### ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed.				
Add GST @ 7%				490.70
Total Amount Payable				\$ 7,500.70

#### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission ..... 13/08/2021 16:04 (SGT)  
Date of Accident ..... 13/08/2021 14:36 (SGT)  
Exact Location of Accident ..... Near 20 Stevens Rd, Singapore  
Additional Location Information ..... Balmoral Park Toward Steven Road  
Country/State of Loss ..... Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SKF2225T

### INSURED/POLICYHOLDER

Is company? ..... No  
Name Of Registered Owner ..... ANG SWEE HIN  
NRIC No ..... SXXXX507A  
Email Address ..... thomas.ang@hotmail.com  
Mobile Phone No ..... (Phone) +65-97916894  
Alternative Phone No ..... (Home) +65-97916894

### VEHICLE PARTICULARS

Manufacturer ..... Honda  
Model ..... Vezel  
Variant ..... VEZEL 1.5X A  
Exact purpose for which vehicle was being used at time of accident ..... Private use  
Are you claiming under your own insurance policy for repair to your vehicle? ..... No - Claiming third party  
Vehicle Category ..... Private car  
Transmission ..... Auto  
CC ..... 1500

### INSURANCE COMPANY

Name of Insurance Company ..... FWD Singapore Pte. Ltd.  
Type of Coverage ..... Comprehensive  
Fleet Policy ..... No  
Policy Number ..... PNPV2017-00003264-04  
Cover Note Number ..... -

### DRIVER

Name of Driver ..... ANG SWEE HIN  
NRIC No ..... SXXXX507A



Date Of Birth ..... 23/05/1968  
 Occupation ..... Outdoor  
 Date Of Driving Pass ..... 15/09/1990  
 Driving experience ..... 30 YEARS AND 11 MONTHS  
 Gender ..... Male  
 Mobile Number ..... (Phone) +65-97916894  
 Alt. Phone Number ..... (Home) +65-97916894  
 Email Address ..... thomas.ang@hotmail.com  
 Address ..... BLK 458 CHOA CHU KANG AVENUE 4 #06-203  
 Address complement ..... -  
 Postcode ..... 680458  
 Is the driver the policyholder? ..... Yes  
 If No, Relationship of the Driver with the Insured ..... -  
 Does Driver Own Other Vehicles? ..... No  
 Vehicle Registration Number of Other Vehicle Owned by Driver ..... -  
 Insurance Company of Other Vehicle Owned by Driver ..... -

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident ..... Collision - Head to Rear  
 Weather Conditions ..... Clear  
 Road Surface ..... Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? ..... No  
 Number of vehicles involved in the accident ..... 2  
 Was anybody injured in the Accident? ..... No  
 Was any injured conveyed to hospital by ambulance? ..... -  
 Was any other vehicle or property damaged? ..... Yes  
 Number of Passengers (Including Driver) ..... 1  
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? ..... No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police? ..... No  
 Was notice of intended Prosecution given? ..... No  
 If yes, against whom? ..... -

#### CIRCUMSTANCES OF ACCIDENT

Refer To Sketch Plan

#### ATTACHMENT(S)

Are accident photos available for attachment? ..... Yes  
 Was there any video captured by Car Camera? ..... Yes  
 Was there any audio recorded? ..... No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number ..... PC6061D  
 Vehicle Manufacturer ..... -  
 Vehicle Model ..... -  
 Vehicle Variant ..... -  
 Vehicle Colour ..... -  
 Vehicle Category ..... Commercial vehicle  
 Name of Driver ..... -  
 Contact Number ..... -  
 Address ..... -  
 Address complement ..... -

Postcode .....  
Insurance Company Name .....  
Nature Of Damage .....  
Details of property damaged in accident .....  
No. Of Passenger (Including Driver) .....



# SKETCH PLAN

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

*[Signature]*

Policyholder's Signature / Date & Time


13 Aug 21, 2:58pm

Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date & Time

*[Signature]*

Witnessed by Reporting Centre Personnel





Describe Circumstances of the Accident

I WAS driving on 13 August about 2.45pm turning right from  
Balmoral Park towards Steven Road. Suddenly the minibus behind  
me hit into my car. The minibus driver (PC 6061D) did not  
keep safety distance from me when making the turn.

No one was travelling with me nor the other minibus and  
no one was injured.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &  
Time

13 Aug 21, 2:55pm

Driver's Signature (If driver is not the policyholder) / Date  
& Time

Witnessed by Reporting Centre  
Personnel





> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	507A
Vehicle No.:	SKF2225T
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Aug 2021
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X A
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	L15B4035713
Chassis No.:	RU11115708
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,752.00
Original Registration Date:	12 May 2016
First Registration Date:	12 May 2016
Transfer Count:	0
Actual ARF Paid:	\$9,752.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 May 2026
PARF Rebate Amount:	\$6,826.00
COE Expiry Date:	11 May 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,009.00
COE Rebate Amount:	\$21,773.00
Total Rebate Amount:	\$28,599.00

The information contained herein is correct as at 17 Aug 2021

OK



# Honda Vezel 1.5A X

[Overview](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

Served SVTA Committee Member Since 2011  
Council of Automobile Megamart MOST 2555  
Committee Member Exoticarsclub

**Price** **\$57,000**

**Depreciation** **\$10,820 /yr**  
[View models with similar depre](#)

**Reg Date** **25-May-2016**  
**(4yrs 9mths 7days COE left)**

**Mileage** **77,000 km (14.7k /yr)**

**Manufactured** **2016**

**Road Tax** **\$682 /yr**

**Transmission** **Auto**

**Dereg Value** **\$29,474 as of today (change)**

**OMV** **\$20,539**

**COE** **\$46,009**

**ARF** **\$10,755**

**Engine Cap** **1,496 cc**

**Power** **96.0 kW (128 bhp)**

**Curb Weight** **1,190 kg**

**No. of Owners** **4**

**Type of Vehicle** **SUV**