

ASS. REC. BY: Steve T

CC3/AIG 2100 8581/GA3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / PRES / OD-RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

at

Insured:

Policy No.

Claims No.

Sum Insured:

(Client's Record)

Excess:

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Sent:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Cum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Locked / Burnt or

Brakes: Inorder / Jammed / Locked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body structure affected due to collision

Date / Time

Action / Instruction

Time/Time, File, Pass to?

☐

: Prel. Report

☐

: Final Report

Time/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Police

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Weekend (\$

Stamp/Signature:

Date/Time/Initials:

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No. 199101494Z
GST No. M200985052



Quotation

Non binding - Preview

Page

1/2

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Mr
AARON
ZHANG YIREN
90 CORPORATION ROAD
#16-22
SINGAPORE 649824

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor

16-08-2021
5211043795
201009404M
30001
2021030742/ 1
16-08-2021
YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SMT2199M	5T13NZC1	31-03-2020	WVGZZZ1TZLW011859	Touran Comfortline EQP 1.4 TSI 110kW DSG	11,310

conting claims: \$967 / OK

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#1	280.00	299.60
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#1	480.00	513.60
5TA833055AL	Door	1	pcs.	2,436.42	#1	2,436.42	2,606.97
5TA839701E 5AP	LHS REAR DOOR	1	pcs.	219.54	#1	219.54	234.91
D 378500A2	Door Seal Outer Black	1	pcs.	43.65	#1	43.65	46.71
	Sound Absorber Laminated	1	pcs.				
8X0831403B	DOOR INSULATOR	1	pcs.	45.17	#1	45.17	48.33
8X4833407B	Door Hinge Half Lower Par	1	pcs.	74.50	#1	74.50	79.72
	DOOR HINGE UPPER (LOWER)	1	pcs.				
8X0831403B	Door Hinge Half Upper Par	1	pcs.	45.17	#1	45.17	48.33
	DOOR HINGE UPPER (UPPER)	1	pcs.				
8X4833405B	Door Hinge Half Lower Par	1	pcs.	44.96	#1	44.96	48.11
	DOOR HINGE LOWER (LOWER)	1	pcs.				
N 91203801	Door Hinge Half Upper Par	2	pcs.	5.17	#1	10.34	11.06
N 91205602	DOOR HINGE LOWER (UPPER)	4	pcs.	3.59	#1	14.36	15.37
5TA839015K	Bolt With Polygon Socket	1	pcs.	419.61	#1	419.61	448.98
	Hex Bolt With Internal To						
	Door Latch	1	pcs.				
	DOOR LOCK						
WHT005504	Fill. Hd. Screw	2	pcs.	2.76	#1	5.52	5.91
5TA839461B	Window Regulator Without	1	pcs.	362.24	#1	362.24	387.60
5TA867211AFDKB	Door Trim Panel	1	pcs.	801.17	#1	801.17	857.25
	LHR DOOR BOARD						
5TA809843	Sectional Part Side Panel	1	pcs.	1,774.72	#1	1,774.72	1,898.95
	LHR FENDER						
D 506KD1A4	2k-Füllschaum	1	pcs.	154.20	#1	154.20	164.99
D 476KD1M2	Sealant Can Be Sprayed	1	pcs.	64.23	#1	64.23	68.73
D 007500A2	Zinc Spray	1	pcs.	68.87	#1	68.87	73.69
D 180003M2	2k-Body Adhesive	1	pcs.	444.39	#1	444.39	475.50
5TA845041ACNVB	Side Window Not Pre-Treat	1	pcs.	333.64	#1	333.64	356.99
	LHR FENDER GLASS						
D 169300M2	1k Window Adhesive	1	pcs.	51.16	#1	51.16	54.74
D 00940104	All Purpose Cleaner	1	pcs.	97.37	#1	97.37	104.19
D 00920002	Primer	1	pcs.	28.44	#1	28.44	30.43
D 181802M1	Activator For Precoated W	1	pcs.	26.15	#1	26.15	27.98
D 00950025	Applicator	2	pcs.	10.44	#1	20.88	22.34
5TA821713D	Stone Protection Foil	1	pcs.	33.81	#1	33.81	36.18
	LHR FENDER FOIL						
	LABOUR	85	pcs.	840.00	#1	5,040.00	5,392.80
	SPRAY PAINT	22	pcs.	800.00	#1	3,200.00	3,424.00
	TRANSFER DOOR MECHANISM	1	pcs.	840.00	#1	840.00	898.80
	R&R LHR FENDER GLASS	1	pcs.	840.00	#1	840.00	898.80
	R&R REAR LUGGAGE TRIM	1	pcs.	840.00	#1	840.00	898.80
	LHR FENDER GLASS	1	pcs.	180.00	#1	180.00	192.60

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz Reg No: 199101494Z
GST No: M200985052



Quotation

Non binding - Preview

Page 2/2

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Mr
AARON
ZHANG YIREN
90 CORPORATION ROAD
#16-22
SINGAPORE 649824

Document no
Document date 16-08-2021
Customer no 5211043795
Customer GST-ID 201009404M
Dealer 30001
Job order number 2021030742/ 1
Job order date 16-08-2021
Service Advisor YEN MEI WONG


License plate SMT2199M	Model code 5T13NZC1	First registration 31-03-2020	VIN WVGZZZ1TZLW011859	Model Touran Comfortline EQP 1.4 TSI 110kW DSG	Mileage 11,310
---------------------------	------------------------	----------------------------------	--------------------------	--	-------------------

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	R&R DOOR BOARD LEATHER AXA ARF VS NTUC 3RD PARTY VEHICLE SMF8688C	1	pcs.	360.00	#1	360.00	385.20

Quotation valid till 23-08-2021

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	18,920.51	7%	1,377.64	19,680.51	21,058.15

Customer



-----VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).-----

Steve (LKK)
18/8/21, 930am

WIL PL
11-12 days
P/P
M Bel Sy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



WePolish SG

87868155

https://www.carousell.sg/we_polish/

wepolishsg@gmail.com

*new
quote.*

INVOICE
INV917

DATE
Aug 16, 2021

DUI
On Receipt

BALANCE DUE
SGD S\$96.00

BILL TO

Mr Aaron (Touran VW)

90 Coporation Road #16-22

☐ 91706089

DESCRIPTION	RATE	QTY	AMOUNT
Diamond Ceramic Coating Partial Door & Rear Panel	S\$48.00	2	S\$96.00

TOTAL SGD S\$96.00

BALANCE DUE SGD S\$96.00

*Steve (CLKK)
18/8/21*

DATE SIGNED
Aug 16, 2021