

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	STRIDES AUTOM	OTIVE SERVICES PTE LTD		Ref:	CS/SMR21008586/R1uf3e2	
	60 WOODLANDS I E4SINGAPORE 75	NDUSTRIAL PARK 37705		Date:	31/08/2021	
				Code:	SMR	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMB 1341U	Veh. Inspected	i	SBS 3396P	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	BUS/08/21/5020	Excess (\$)		0.00	
	Assign From	HUA YEN	Assign Date		16/08/2021	
2.	Vehicle Particulars & Condition					
	Make & Model	VOLVO B9TL 9.4L AUTO	c.c		9364	
	Engine No.	HIDDEN	Year of Reg.		2014	
	Chassis No.	YV3S4P923EA167319	Colour		GREEN	
	Odometer	427777 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	FAIR				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	275/70 R22.5	MICHELIN		8 mm	
	L/H Front Tyre	275/70 R22.5	MICHELIN		8 mm	
	R/H Rear Tyre	275/70 R22.5 (D)	MICHELIN		8/8 mm	
	L/H Rear Tyre	275/70 R22.5 (D)	MICHELIN		8/8 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	05/08/2021	Inspection Dat	e	18/08/2021	
	Survey held at	TOWER TRANSIT SINGAPORE	PTE. LTD.			
		21 BULIM DRIVE SINGAPORE 648170				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:		2 Work	ing Days	