ESTIMATED ACCIDENT REPAIR COST



ACCIDENT TIME			1	BUS REGISTRATION	Τ	
REPORTED	17:08HRS			NUMBER	SBS3396P	
ACCIDENT DATE	05-A	ug-21		BUS TYPE (SD/DD)	DD	
BUS CAPTAIN NAME WONG KAI WENG				BUS ROUTE NUMBER		
THIRD PARTY CLAIM AGAINST	SMRT -	MSFCIL		BUS ADVERTS (Y/N)	N	
SECTION 1 : ASSESS	MENT / REPAIR / SP	RAY PAINT (LABOUR	R COST)			
LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)						TOTAL COST
TO PERFORM REPAIR WORKS ON :- • OSR DOME FIBER GLASS BODY						\$650.00
SPRAY PAINTING :- • OSR DOME FIBER GLASS BODY						\$640.00
SPRAY PAINTING \$640 P	ER PANEL				7% GST	\$90.30
LABOUR CHARGES \$650 PER DAY					LABOUR TOTAL COST	\$1,380.30
SECTION 2 : RECOV	ERY OF ACCIDENT BU	JS (TOWING COST)				
			TOTAL TOWING COST			-
SECTION 3 : NUMBI	ER OF DAYS BUS IN V	VORKSHOP FOR SUR	EVEY & REPAIRS			
DATE IN						
					DATE & TIME SURVEY	
				-	DATE OUT	
		BUS TYPE (SD / DD)	DD		TOTAL NUMBER OF DAYS	
			LOSS OF USE COST			\$1,200.00
		SUMMAR				RY
					SECTION NO.	соѕт
					1	\$1,380.30

PAGE 1

\$1,200.00

\$2,580.30

3

TOTAL