



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile          |                |                                                                                                      |                                                           |            |
|----------------------------------------------------------------------------|----------------|------------------------------------------------------------------------------------------------------|-----------------------------------------------------------|------------|
| AXA INSURANCE PTE LTD<br>8 SHENTON WAY #24-01<br>AXA TOWERSINGAPORE 068811 |                |                                                                                                      | Ref: CS3/ASM21008600/Gvc<br>Date: 17/08/2021<br>Code: ASM |            |
| <b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>                        |                |                                                                                                      |                                                           |            |
|                                                                            | Insured Veh.   | YM 6498T                                                                                             | Veh. Inspected                                            | SMD 800H   |
|                                                                            | Policy No.     |                                                                                                      | Coverage (\$)                                             | 0.00       |
|                                                                            | Claim No.      | S1M03FAA                                                                                             | Excess (\$)                                               | 0.00       |
|                                                                            | Assign From    | ANG Yvonne                                                                                           | Assign Date                                               | 17/08/2021 |
| <b>2. Vehicle Particulars &amp; Condition</b>                              |                |                                                                                                      |                                                           |            |
|                                                                            | Make & Model   |                                                                                                      | c.c                                                       | 0          |
|                                                                            | Engine No.     | HIDDEN                                                                                               | Year of Reg.                                              |            |
|                                                                            | Chassis No.    |                                                                                                      | Colour                                                    |            |
|                                                                            | Odometer       | -                                                                                                    | Steering                                                  |            |
|                                                                            | Brakes         |                                                                                                      | Modification                                              |            |
|                                                                            | General        |                                                                                                      |                                                           |            |
| <b>3. Conditions of Tyres</b>                                              |                |                                                                                                      |                                                           |            |
|                                                                            |                | Size                                                                                                 | Make                                                      | Balance    |
|                                                                            | R/H Front Tyre |                                                                                                      |                                                           | mm         |
|                                                                            | L/H Front Tyre |                                                                                                      |                                                           | mm         |
|                                                                            | R/H Rear Tyre  |                                                                                                      |                                                           | mm         |
|                                                                            | L/H Rear Tyre  |                                                                                                      |                                                           | mm         |
| <b>4. Description of Damages</b>                                           |                |                                                                                                      |                                                           |            |
|                                                                            |                |                                                                                                      |                                                           |            |
| <b>5. General Information</b>                                              |                |                                                                                                      |                                                           |            |
|                                                                            | Accident Date  | 08/07/2021                                                                                           | Inspection Date                                           | 17/08/2021 |
|                                                                            | Survey held at | REVOL CARZ GARAGE PTE LTD<br>BLOCK 10, ANG MO KIO IND PARK 2A #02-18, AMK AUTOPOINT SINGAPORE 568047 |                                                           |            |
| <b>5a. Remarks</b>                                                         |                |                                                                                                      |                                                           |            |
|                                                                            |                |                                                                                                      |                                                           |            |