

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM21008600/Gvce2	
	8 SHENTON WAY SINGAPORE 0688	#24-01 AXA TOWER 11		Date:	23/08/2021	
	ATTN: ANG YVON	NE		Code:	ASM	
1.	. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	YM 6498T	Veh. Inspected	k	SMD 800H	
	Policy No.	GA542633	Coverage (\$)		0.00	
	Claim No.	S1M03FAA	Excess (\$)		0.00	
	Assign From	ANG YVONNE	Assign Date		17/08/2021	
2.	Vehicle Particulars & Condition					
	Make & Model	MERCEDES BENZ E 250	c.c		1796	
	Engine No.	HIDDEN	Year of Reg.		2010	
	Chassis No.	WDD2120472A148039	Colour		BROWN	
	Odometer	108015 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	245/40 R18	PIRELLI		6 mm	
	L/H Front Tyre	245/40 R18	PIRELLI		6 mm	
	R/H Rear Tyre	245/40 R18	PIRELLI		6 mm	
	L/H Rear Tyre	245/40 R18	PIRELLI		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.					
5.	5. General Information					
	Accident Date	08/07/2021	Inspect Date /	Time	17/08/2021 (12:00 PM)	
	Survey held at	urvey held at REVOL CARZ GARAGE PTE LTD				
	BLOCK 10, ANG MO KIO IND PARK 2A #02-18, AMK AUTOPOINT SINGAPORE 568047					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					

Report Ref No. CS3/ASM21008600/Gvce2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor