



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21008614/Uuf3n2	
			Date: 27/08/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YN 5710G	Veh. Inspected	SMJ 8385E
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2102455/THE	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	17/08/2021
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN SYLPHY (A)	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	MNTBBAB17Z0034564	Colour	GREY
	Odometer	42468 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/60 R16	BRIDGESTONE	6 mm
	L/H Front Tyre	195/60 R16	BRIDGESTONE	6 mm
	R/H Rear Tyre	195/60 R16	BRIDGESTONE	6 mm
	L/H Rear Tyre	195/60 R16	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	16/08/2021	Inspection Date	17/08/2021
	Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	