



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21008616/Ttcn2	
			Date: 10/02/2022	
			Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHD 6356T	Veh. Inspected	GBB 7502M	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/08/21/2024	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	17/08/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	CITROEN BERLINGO 1.6	c.c	1560	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	VF77F9HXC9J246361	Colour	BLACK	
Odometer	355422 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/65 R15	MICHELIN	6 mm	
L/H Front Tyre	205/65 R15	MICHELIN	6 mm	
R/H Rear Tyre	205/65 R15	MICHELIN	6 mm	
L/H Rear Tyre	205/65 R15	MICHELIN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	11/08/2021	Inspection Date	01/09/2021	
Survey held at	SYNERGY BUILDING, KAKI BUKIT #01-44			
Repairer	TSL AUTO GARAGE			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	