## MG SOLUTION PTE LTD

23 Kaki Bukit Ave 4 (South Wing) #0 4 -0 | Vicom Inspection Centre, Singapore 415933 Tel: 6243 1373 Fax: 6243 1376

Co. Reg. No. : 201427944N		
Date: IXI8/n		
TO : AXA /MURANCE SIMAPORE Tel : (800 - 8804741	E P76 L70	By Fax & Email
Fax: Email: motor-survey @axa, (um. sg		
Attn: Motor Claims Department		
Dear Sir,		
Re: Accident involving motor vehicle No along PREMISES OF FUHUA SEC	SIN 6139 and _ SCHOOL NOT JURUA WEST ST	5HC 7773R 6 on 17/8/21
We are instructed by JA (OBS DOWNE EGBERTS RTL (Name of Claimant) to notify you of a road traffic accident on the above mentioned. A copy of the Singapore Accident Statement / Traffic Police Report filed is enclosed.		
As a result of the accident, our client's / customer's vehicle has been damaged. Before our client / we proceed to repair the damaged vehicle, please let us know within <b>2 working days</b> of your receipt of this notice whether you or your insurer would like to conduct a <b>Pre- Repair Survey</b> of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client / we shall proceed to repair the vehicle without further reference to you.		
Thank you.	FOR SURVEYOR	
Yours faithfully,	Please initial here after complination. Thank you.	etion of pre-repair
SOUTION SEE	Appointed Surveyor: (Name & Signature)	ě
MS HENG YOU'R HONG	Date & Time of Inspection:	

HP: 9188 6931