

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email: mg3solution@gmail.com

TO	: AXA	DATE	: 23-Aug-21
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: SJN613P		
MODEL	: TOYOTA ALPHA 2.5		
CHASSIS NO			
ACCIDENT DETAILS		DATE	: 12-Aug-21
		TIME	: 08:10HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT FENDER LH <i>Dented</i>	1	\$ 788.50	\$ 788.50
2	FRONT DOOR LH <i>Dented</i>	1	\$ 1,588.20	\$ 1,588.20
3	FRONT DOOR OUTER GARNISH <i>Dented</i>	1	\$ 580.30	\$ 580.30
4	REAR SLIDING DOOR LH <i>Repair</i>	1	\$ 1,855.20	\$ 1,855.20
5	REAR SLIDING DOOR OUTER GARNISH <i>Repair</i>	1	\$ 512.50	\$ 512.50

TOTAL PRICE \$ 5,324.70

LESS 25% \$ 1,331.18

SUB TOTAL PRICE \$ 3,993.53

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT DOOR OUTER GARNISH CLIPS(SET) <i>NE</i>	1	\$ 22.00	\$ 22.00
2	SLIDING DOOR OUTER GARNISHCLIPS(SET) <i>NE</i>	1	\$ 22.00	\$ 22.00

TOTAL \$ 44.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,000.00	500	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,000.00	700	

3	TUFF COAT	\$ 180.00	50	
4	WIRING CHECK	\$ 150.00	X	
5	TO REMOVE AND REFIX FRONT DOOR MECHANISH	\$ 100.00	80	
6	TO REMOVE AND REFIX REAR DOOR MECHANISH	\$ 120.00	X	

1330

TOTAL \$2,550.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 4,037.53
TOTAL LABOUR COST : \$ 2,550.00
TOTAL REPAIR COST : \$ 6,587.53

Adrian L
L/s 24/08/21
04 Days.

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :
PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

total: 3569.75
L/s 2850

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: