

ASS. REC. BY: Steve REPT: CC4/11121008631/RA3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TPRES / OD-RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Sent:

Consistent? : Yes or No

Est. Repair:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

YP 2678B

Yr Regn:

17/5/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

ISUZU

NPR 85

C.C.

2499

Colour:

White

A/C: Insured / Std / NI / N

Sp. Reading

117480

T/Radio: Insured / Std / NI / N

Eng/No:

C/N:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Locked / Burnt or

Brake: In order / Jammed / Locked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

195/85 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

4

mm

U/Bal.

4

mm

D.O.A.

7/8/21

D.O.L.

18/8/21

Survey held at

Cycle & Collage

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MP-43K

Time/Date, File, Poss. to



Prell. Report



Final Report

Time/Date, File Return to

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Insp (\$



Weekend (\$

Survey Fee:

Transportation

\$ + RS \$

Photos

Others

TOTAL

NGEE NGEE MOTOR

Blk K No 22 Pandan Loop,
Singapore 128240

Tel : (65) 6777 5382 Fax : (65) 6777 1627

GST No.

1799

QUOTATION

Quot To :

INDIA INTERNATIONAL INSURANCE PTE LTD

Attn :

Tel :

Fax :

Date : 16-08-2021

Terms : CASH

Sales Rep :

Vehicle No. : YP 2678 B

S/No.	Product Code	Description	Quantity	Price	Amount
		RH/LH SIDE LAMP ASSY	2	135.00	270.00
		RH HEAD ASSY	1	1.00	450.00
		FRONT PANEL	1		780.00
		FRONTGRILLED	1		450.00
		FRONT GRILLED CLIP	8	5.00	40.00
		WELDING AND CUT FRONT PANEL			850.00
		AND REPLACE FRONT PANELAND			
		REALIGNMENT FRONT BODY AND FIX			
		LIGHTING SYSTEM			
		REPRAYING AREA			550.00
		LABOUR CHARGE FOR LIGHTING			50.00
		SYSTEM			

Total	3,440.00
Discount@	
Sub-Total	3,440.00
GST@ 0 %	
Grand-Total	\$3,440.00

Three Thousand Four Hundred Forty Only

the Repairer of the following:

- To rectify before/after spray painting
- To display damaged part(s) for survey
- Parts prices are subject to quotation
- Third party survey to be on "No Prejudice" basis

This is computer generation document

No Signature is required

in accordance with the policy conditions and the Insurance Company

Acknowledged by Repairer

Signature:

Date:

NGEE NGEE MOTOR

BLK K, NO. 22 PANDAN LOOP

SINGAPORE 128240

Tel : 6777 5382, 6777 1627

Customer Chop and Signature

SS1F218E0001 / SNG AH TEE MOTOR & PANEL SERVICE PTE LTD
ENTRY DATE & TIME: 14/08/2021 13:48 (SGT)
SUBMITTED BY: JOYCE TAN
VERSION: 1 (14/08/2021 13:48 (SGT))

Your NCD will be affected due to late reporting

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	14/08/2021 13:48 (SGT)
Date of Accident	07/08/2021 14:30 (SGT)
Exact Location of Accident	33 Harbour Dr, Singapore 117606
Additional Location Information	INSIDE PSA PASIR PANJANG
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP2678B
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	MATRIX MARINE LOGISTICS & SUPPLIES PTE. LTD.
Company Reg No	2XXXXX241R
Email Address	matrix@matrix-supply.com.sg
Mobile Phone No	(Phone) +65-96756815
Alternative Phone No	(Office) +65-63522381

VEHICLE PARTICULARS

Manufacturer	Isuzu
Model	NPR85UH5A
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Manual
CC	2999

INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	GA570694
Cover Note Number	-

DRIVER

Name of Driver	WIN ZAW MIN
NRIC No	GXXXXX936M

Date Of Birth	23/11/1978
Occupation	Outdoor
Date Of Driving Pass	19/11/2019
Driving experience	1 YEAR AND 9 MONTHS
Gender	Male
Mobile Number	(Phone) +65-82857481
Alt. Phone Number	-
Email Address	matrix@matrix-supply.com.sg
Address	BLK 122A EDGE DALE PLAINS #09-171 PUNGGOL EDGE
Address complement	-
Postcode	821122
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Nanyang Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18007929999
Alt. Police Station Phone No	(Fax) +65-67912972
Police Station Address	No. 2 Jurong West Avenue 5 Singapore 649482
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO POLICE REPORT T/20210812/2058

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY:

Vehicle Registration Number	GBE1658X
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle

Name of Driver	SNG WEE SENG
NRIC No	SXXXX590Z
Contact Number	(Phone) +65-91559739
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

- [illegible]

THE POLICE HAVE BEEN ADVISED THAT THE ABOVE NAMED PERSONS ARE NOT TO BE HELD RESPONSIBLE FOR ANY DAMAGE TO OR LOSS OF ANY PROPERTY OR PERSONS.




the night before.

forputing centres. The overall significance
 is given by

$$F = \frac{1}{n} \sum_{i=1}^n \frac{1}{\sigma_i^2} \left(\frac{1}{n} \sum_{j=1}^n \frac{1}{\sigma_j^2} \right)$$

SKETCH PLAN #2

SKETCH PLAN #2



A - 7P2C45B

B - 68L10587

PSA Pasir Panjang

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

From to Date Report 1/20/08/12/2058

Report I was outbase driver to drive 7P2C45B for working purpose at the accident time

DECLARATION

I hereby declare that the information provided is true and correct to the best of my knowledge.



[Signature]
 Name of Driver
 Date & Time



☐ Date of accident
☒ Date of report
☒ Date of investigation
☐ Date of completion
 Name: Ngee Ann
 Address: 7P2C45B

Reporting Centre Personnel's Signature
 Name:
 Mobile No:

6563522383

NOTICE OF REPORTING

Annex D

This is to confirm that Sng Wee Seng, NRIC: S6819590Z, HP: 91559739 has reported to the Police a non-injury traffic accident which occurred along PSA Berth P34 on 7/8/2021 at about 2.30pm involving the following vehicles:

1 On 7/8/21 at about 2.30pm, I was driving my vehicle GBE1658X (lorry) and had stopped my vehicle as I am queuing to exit the lane. I then reversed my vehicle to change lane and collided with the vehicle(lorry) that was behind me. We exchange particular. The driver is namely Win Zaw Min, G7160936M and driving for company named Matrix Marine Logs & SUPP P L. No visible injuries on all parties. My vehicle is under my company named Reefertec Pte Ltd.

2 If this accident was reported to the Police within 24 hours of its occurrence, then he/she has complied with Sec 84(2) of the Road Traffic Act, Cap 276.

Rank/Name of Issuing Officer: SGT(3) T140415 Nurjannah

Date: 08/08/2021 Time: 0110hrs

S/D Ref: -

Police Post/Unit : Bukit Merah West NPC

Original - to be issued to informant
Duplicate - to be submitted to Traffic Police

Noted
Name
Date
Signature



6563522383



SINGAPORE POLICE FORCE

Police Station Of Origin:
Nanyang N.P.C.
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999



T/20210812/2058

1 of 3

Report No. T/20210812/2058

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:
12/08/2021 15:59

Vide Report No.:

Station Diary No.:
15

Informant's Particulars

Name of Informant:

WIN ZAW MIN

Address:

APT BLK 122A EDGEDALE PLAINS #09-171 PUNGGOL
EDGE SINGAPORE 821122

ID Type / ID No.:

FIN NO / G7160936M

Contact No.:

Home/Office:

Mobile: 82857481

Nationality:

MYANMAR

Email:

Sex:

Male

Age:

42

Date of Birth:

23/11/1978

Type of Informant:

Driver

Race:

Burmese

Language:

Institution / School Name:

Occupation:

Lorry driver

Driving Licence Information:

Class: 3,4

Date of Expiry:

General Information of the Accident

Type of
Accident:

Non-Injury

Drink
Drive:
No

Date/Time of
Accident:

07/08/2021 14:30

Type of Location:
PSA BERTH P34

Location:

HARBOUR DRIVE

Weather:

Clear

Road Surface:

Dry

Road Speed Limit:

Traffic Flow:

Traffic Control:

Not Controlled

Traffic Volume:

Heavy

Type of Collision:

Moving Vehicle Against - Parked Vehicle

Anyone conveyed by
ambulance:

No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBE1658X	Lorry				No Damage	0
YP2678B	Lorry				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No

No. of Pedestrians Injured: Nil

Use of Pedestrian Crossing: NA



SINGAPORE
POLICE FORCE

6563522383

0002/0003

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999



T/20210812/2058

2 of 3

Report No. T/20210812/2058

CONTINUATION OF REPORT

Name	SNG WEE SENG			ID No.	S6819590Z
Related Vehicle	GBE1658X (Lorry)			Contact No.	91559739
Hospital/Clinic	NIL			Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL			Date Discharge	NIL
No. of Days granted Medical Leave	NIL			Degree of Injury	NIL
Driver					
Name	WIN ZAW MIN			ID No.	G7160936M
Related Vehicle	YP2678B (Lorry)			Contact No.	82857481
Hospital/Clinic	NIL			Class of Driving Licence & Expiry Date	Class: 3,4 Date of Expiry: NIL
Date Treatment	NIL			Date Discharge	NIL
No. of Days granted Medical Leave	NIL			Degree of Injury	NIL

Brief Details.

On 07/08/2021 at around 1430hrs, I was driving my lorry along PSA Berth P34, bearing the plate number YP2678B and had stopped my vehicle as I am queuing to exit the lane. While I was waiting in the queue, my vehicle was in a stationary position and suddenly, the lorry in front of me bearing the plate number GBE1658X reversed his vehicle to change lane and collided on to my front of my lorry. My front of my lorry was slightly damaged and the lorry GBE1658X was not damaged. We then exchanged particulars and the owner of GBE1658X was namely Sng Wee Seng, NRIC S6819590Z, HP91559739. No one was injured as there is no visible injuries on all parties. No police and ambulance was called. No government property was damaged.

I am here to make a police report about this matter for record purposes.

6563522383

**SINGAPORE
POLICE FORCE**

T/20210812/2058

3 of 3

Report No. T/20210812/2058

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J/

SC2 ZHAN YUE SHENG, JACKSON

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIA /

SI TAN JEOK LENG

Contact No.: 65476151

Authentication Stamp

P168

Signature Of Informant:

Date/Time:

12/08/2021 15:59

Classification Of Case:

SIGNATURE