

(08/11/13) wef  
ASS. REC. BY: Am

REF:

CS3/AM21008641/R1H3

7416

### ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMN 1723

at Workshop m/s HIAP LOK AUTOMOBILE

of 160/SIN MINH DR #105-17 ANTOCITY

Insured:

AM

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

152k

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMN 1723

Yr Regn:

2019 / July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

VOLKSWAGEN GOLF GTI 2.0 c.c. 1984

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

26095

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WVW222AM ZKW 124918

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/40R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

17/08/21

D.O.I.

07/09/21

Survey held at

HIAP LOK AUTOMOBILE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair limit - 90k

**SUBMIT DAR REPORT**

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐  
☐  
☐  
☐

: Site Insp (\$

: Interview (\$

: Tech. Invs (\$

: Weekend (\$

) : S + RS, SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I. (\$

TOTAL



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	17/08/2021 15:17 (SGT)
Date of Accident	17/08/2021 09:30 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	JUNCTION BETWEEN PAYA LEBAR ROAD AND GEYLANG EAST CENTRAL
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SMN172J

#### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	TAY KIAN SENG, JOHN
NRIC No	S7244741G
Email Address	tayksj@gmail.com
Mobile Phone No	(Phone) +65-92738007
Alternative Phone No	+65-92738007

#### VEHICLE PARTICULARS

Manufacturer	Volkswagen
Model	Golf
Variant	Golf GTI 2.0   TSI 169kW DSG
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2000

#### INSURANCE COMPANY

Name of Insurance Company	FWD Singapore Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	PNPV2020-00006580-01
Cover Note Number	-

#### DRIVER

Name of Driver	TAY KIAN SENG, JOHN
----------------	---------------------

NRIC No	S7244741G
Date Of Birth	26/11/1972
Occupation	Indoor
Date Of Driving Pass	05/08/1992
Driving experience	29 YEARS
Gender	Male
Mobile Number	(Phone) +65-92738007
Alt. Phone Number	+65-92738007
Email Address	tayksj@gmail.com
Address	BLK 133 GEYLANG EAST AVE 1
Address complement	#07-207
Postcode	380133
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Change/cross lane
Weather Conditions	Raining
Road Surface	Wet

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO SKETCH PLAN & VIDEO

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMN1389U
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	ARSALLAH KHAN BIN MOHD DIN
NRIC No	S1217680E
Contact Number	(Phone) +65-82883145



Address -  
Address complement -  
Postcode -  
Insurance Company Name -  
Nature Of Damage -  
Details of property damaged in accident -  
No. Of Passenger (Including Driver) -

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

17/8/2021 / 240 PM


Driver's Signature  
(If driver is not the policyholder)  
Date & Time

Reporting Centre Personne's Signature  
Name:  
NRIC/F N No.:

17/8/2021



## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- 1) AROUND 9.30 AM ON 17 AUG 2021, I WAS TRAVELING IN CAR SMN 172J ALONG PAYA LEBAR ROAD. I WANTED TO TURN INTO GEYLANG EAST CENTRAL.
- 2) CAR SMN 1389U ENCROACHED INTO MY LANE WITHOUT SIGNALING AND I JAMMED BRAKE.
- 3) AFTER I JAMMED BRAKE, MY CAR REMAINED STATIONARY. AS CAR SMN 1389U STARTED TO MOVE, IT TURNED SLIGHTLY INTO MY LANE AGAIN WITHOUT SIGNALING, AND ITS <sup>RIGHT</sup> BACK SCRAPED THE FRONT LEFT OF MY CAR.
- 4) I attach a video recording of my description above.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time

17/8/2021

240PM

Driver's signature  
(If driver is not the policyholder)  
Date & Time

Reporting Centre Personnel's Signature  
Name:  
NSIC/PA No.:

17/8/2021



## Condition (CON)

(1) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched  
 (7) Deformed (8) Shifted (9) Buckled (10) Broken (11) Necessary (12) Missing  
 (13) Torn (14) Unconfirmed (15) Not Working

## ACTION (AC)

(1) Replace (✓) (2) Repair (X) (3) Check (?)  
 (4) Not Consistent (NC)

## MOTOR CAR (LH)

SLM 1723

Vehicle No:

## Left Portion

NAC	INC	Item	CON	AC	Qty
1255	995326	Frt LH Door			
1256	995140	Frt LH Door Protector			
1257	995104	Frt LH Door Hinge			
1258	995142	Frt LH Door Wing Mirror			
1259	995102	Frt LH Door Garnish			
1260	991593	Frt LH Door Glass Outer Moulding			
1261	991588	Frt LH Door Glass Inner Moulding			
1262	995103	Frt LH Door Glass			
1263	991595	Frt LH Door Glass Regulator			
1264	991596	Frt LH Door Glass Regulator Motor			
1265	991662	Frt LH Door Rubber			
1266	991636	Frt LH Door Outer Handle			
1267	991607	Frt LH Door Inner Handle			
1268	991625	Frt LH Door Lock w/Key			
1269	991624	Frt LH Door Lock			
1270	991562	Frt LH Door Central Lock			
1271	991675	Frt LH Door Switch			
1272	991617	Frt LH Door Inner Trim Board			
1273	991568	Frt LH Door Checker			
1274	991575	Frt LH Door Felt			
1275	991688	Frt LH Door Wire Harness			
1276	991683	Frt LH Door Window Glass Pillar			
1277	991640	Frt LH Door Outer Pillar			
1278	991613	Frt LH Door Inner Pillar			
1279	991646	Frt LH Door Pillar Inner Garnish			
1280	990554	Centre Pillar LH			
1281	990542	Centre Inner Pillar LH			
1282	990517	Centre Pillar Upper Garnish LH			
1283	990564	Centre Pillar Lower Garnish LH			
1284	991670	Frt LH Door Step Garnish			
1285	994052	Rocker Panel LH			
1286	994049	Rocker Panel Inner Panel LH			
1287	994046	Rocker Panel Garnish LH			
1288	994055	Rocker Panel Outer Side Skirt LH			
1004	991300	Frt Bumper		scr	
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1029	995153	Frt LH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1096	995070	Frt LH Fender		bf	✓
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
		Frt LH Fender Emblem		nec	✓
		Frt LH Wheel Rim		scr	✓

NAC	INC	Item	CON	AC	Qty
1289	995156	Rear LH Door			
1290	993282	Rear LH Door Protector			
1291	995194	Rear LH Door Hinge			
1292	993228	Rear LH Door Garnish			
1293	993278	Rear LH Door Glass Outer Moulding			
1294	993231	Rear LH Door Glass Inner Moulding			
1295	995190	Rear LH Door Glass			
1296	993238	Rear LH Door Glass Regulator			
1297	995192	Rear LH Door Glass Regulator Motor			
1298	993294	Rear LH Door Rubber			
1299	993275	Rear LH Door Outer Handle			
1300	993250	Rear LH Door Inner Handle			
1301	993261	Rear LH Door Lock			
1302	993256	Rear LH Door Inner Trim Board			
1303	993218	Rear LH Door Checker			
1304	993230	Rear LH Door Glass Channel			
1305	993242	Rear LH Door Glass Triangle Garnish			
1306	993285	Rear LH Door 1/4 Glass			
1307	993288	Rear LH Door 1/4 Glass Rubber			
1308	993287	Rear LH Door 1/4 Glass Pillar			
1309	993305	Rear LH Door Step Garnish			
1310	993309	Rear LH Door Switch			
1311	994070	Roof Top Panel			
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag			
1314	994084	Roof Top Air-bag Sensor			
1315	994083	Roof Top Air-bag Control Unit			
1141	992958	Rear Bumper			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1151	993077	Rear Bumper Sponge			
1153	993040	Rear Bumper Protector			
1155	993026	Rear Bumper Moulding			
1157	993023	Rear Bumper Lower Spoiler			
1163	993851	Rear LH Taillamp			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1136	990247	Sticker			

3 days

No of Items: \_\_\_\_\_

Assessor: \_\_\_\_\_



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	741G
Vehicle No.:	SMN172J
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Sep 2021
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	GOLF GTI 2.0 DSG
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	CHH306270
Chassis No.:	WWZZZAUZKW124918
Maximum Power Output:	169.0 kW (226 bhp)
Open Market Value:	\$35,044.00
Original Registration Date:	23 Jul 2019
First Registration Date:	23 Jul 2019
Transfer Count:	0
Actual ARF Paid:	\$41,062.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Jul 2029
PARF Rebate Amount:	\$30,796.00
COE Expiry Date:	22 Jul 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$39,406.00
COE Rebate Amount:	\$31,026.00
Total Rebate Amount:	\$61,822.00

The information contained herein is correct as at 07 Sep 2021

OK



# Volkswagen Golf GTI 5DR

[Overview](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)RENTCARLEASE PTE LTD in affiliation with

## COMPLETE CAR TRADE SOLUTIONS

Price **\$145,900**

Depreciation ⓘ \$16,820 /yr  
[View models with similar depre](#)

Reg Date 27-Feb-2019  
(7yrs 5mths 19days COE left)

Mileage 42,000 km (16.6k /yr)

Manufactured ⓘ 2018

Road Tax ⓘ \$1,194 /yr

Transmission Auto

Dereg Value ⓘ \$56,720 as of today ([change](#))

OMV ⓘ \$34,524

COE ⓘ \$35,403

ARF ⓘ \$40,334

Engine Cap 1,984 cc

Power 169.0 kW (226 bhp)

Curb Weight ⓘ 1,408 kg

No. of Owners ⓘ 1