



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21008649/Avf3e2	
			Date: 11/10/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YP 1040Y	Veh. Inspected	SJM 6540G
	Policy No.	D21MTPCVE000258	Coverage (\$)	0.00
	Claim No.	CMTD2102401/IJH	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	18/08/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA WISH	c.c	1794
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	JTDER12W703001633	Colour	WHITE
	Odometer	294261 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	FALKEN	6 mm
	L/H Front Tyre	195/65 R15	FALKEN	6 mm
	R/H Rear Tyre	195/65 R15	FALKEN	6 mm
	L/H Rear Tyre	195/65 R15	FALKEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	11/08/2021	Inspection Date	18/08/2021
	Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	