

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SH 7622S

Make : HYUNDAI

Model : IONIQ(G3)

Date: 16/08/2021

Insurance: NTUC

MVA: MS. LOKE YY

PIP

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			<i>RY</i> \$459.40
10	REAR BUMPER CLIPS			<i>hel</i> \$22.00
1	REAR FENDER LH			<i>RY</i> \$1,768.30
1	REAR BUMPER SIDE BRACKET LH			<i>7</i> \$55.80
	SUB TOTAL			\$2,305.50
	LESS 20%			\$461.10
	DISCOUNTED TOTAL			\$1,844.40
1	REAR DOOR COMFORTDELGRO APPS STICKER LH			<i>nel</i> \$80.00 <i>Nett</i>
1	REAR FENDER PETROL STICKER			<i>net</i> \$15.00 <i>Nett</i>
1	REAR BUMPER RUBBER MAT			<i>x</i> \$50.00 <i>Nett</i>
				\$65.00
	Labour Charge			
	PANEL BEATING			<i>700</i> \$950.00
	SPRAY PAINTING CHARGE			<i>6750</i> \$850.00
	TUFF KOTE			<i>x</i> \$60.00
	REMOVE/ REFIX CUSHION & UPHOLSTERY REAR			<i>60</i> \$120.00
	TOTAL LABOUR			\$1,980.00
	ESTIMATE TOTAL			\$3,889.40

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 97415749
WP 16/8/21 0420pm
P/O Resurvey new parts
Tanpin C/Management
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order: 4108780

JC NO.: 305483000

CUSTOMER

R/MS COMFORT TRANSPORTATION PTE LTD
CUSTOMER NO. 7010045
ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
TEL (R) 65508755 (O)

SCOUT CARD NO


REGN NO.: SH 7622S	MILEAGE
MAKE : HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G3)	DATE/TIME IN 16.08.2021 08:51
YR OF MANU 14.11.2019	TARGET DATE
CHASSIS CODE KMHC851CVLU188667	COMPLETION DATE/TIME

Accident Date: 15.08.2021
NATURE: 3P 15.08.2021

S/NO LABOR CODE

JOB DESCRIPTION

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Vehicle No.: SH 7622S YY

Exit Pass

Vehicle No.: SH 7622S

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard