

ASS. REC. BY: Tan Jkh

REF: NS/ INC 21008654/T1vc

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: **FBH 287Z**
Policy No. _____
Claims No. **MT/1141426-002**
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: Juman
Vehicle: IN / OUT

Veh No: SMA 6998G Yr Regn: 2019 July
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Kyuden Tong C.C. 1580
Colour Blue A/C: Insured / Std / NI / NA
Sp. Reading 305430 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: RMHCS1 CVK416424
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modl: NII / S/Rim / STD A/Rim or
Tyre Size: F: 195/65R15
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Wstake
Front: _____ Rear: _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. _____ mm
D.O.A. 14/8/21 D.O.I. 16/8/21
Survey held at Comfort Logans
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
20/8/21	LS \$1300 confirmed by email (Red 828,38%)

Date/Time, File Pass to? ☐ : Preli. Report
1) ☐ : Final Report
Date/Time, File Return to?
2) 20/8-21-Typist
Report Format: TP
Lump Sum / L.C.R. (F LS \$1300)

Days Of Repair: 2
Resurvey No. of Trip: 1
Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)
Survey Fee: _____
Transportation: _____
S + RS. SI _____
Photos _____
Others _____
TOTAL _____

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

NEW-CLGum)

Date: 16.08.2021
Time: 09:39:16
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305482823
REGN NO : SHA6998G
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 17.07.2019
DATE/TIME IN : 14.08.2021 10:35
ACCIDENT DATE : 14.08.2021

JOB / PARTS DESCRIPTION QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G COVER-RR BUMPER#	1	459.40	20.00	367.52	am
0002 04-01-0104-2533-G MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00	at
0003 04-01-0104-2544-G CAP-RR HOOK	1	98.80	20.00	79.04	am
0004 04-01-0101-0111-G BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	am
0005 09-01-9999-0068-A REVERSE SENSOR ASSY*	1 N	180.00	10.00	162.00	am
0006 04-01-0104-2288-G BEAM-RR BUMPER	1	394.80	20.00	315.84	?
0007 28-01-0104-2029-A VEHICLE NUMBER PLATE REAR	1 N	50.00	10.00	45.00	A
SUB-TOTAL :					1,348.00

JOB NATURE

0000 PB	PANEL BEATING	400.00	350
0001 SP	SPRAYPAINT CHARGE	300.00	250
0002 L	REMOVE/REFIX REVERSE SENSOR	80.00	30
SUB-TOTAL :		780.00	

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 16.08.2021

Time: 09:39:16

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305482823
REGN NO : SHA6998G
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 17.07.2019
DATE/TIME IN : 14.08.2021 10:3
ACCIDENT DATE : 14.08.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 2,128.00

MVA NAME & SIGNATURE
DATE : 16/8/21

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Tanphic 97445749
'up' 16/8/21 e 945
45 Resurvey after repair
Tanphic cllk auto.com
02 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305482823

MEMBER NO. 7010045

383 SIN MING DRIVE

Singapore SINGAPORE 575717

65508755 (O)

REGN NO.: SHA6998G	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G2)	DATE/TIME IN 14.08.2021 10:35
YR OF MANU 17.07.2019	TARGET DATE
CHASSIS CODE KMH8351CVKU164924	COMPLETION DATE/TIME:

JOINT CARD NO.

Accident Date: 14.08.2021

NATURE: 3P 14.08.2021

S/NO	LABOR CODE	DESCRIPTION
------	------------	-------------

FRONT

LEFT SIDE

RIGHT SIDE

REAR

WORKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Exit Pass

Vehicle No.: SHA6998G

No.: SHA6998G JU NTUC LKK

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	14/08/2021 17:35 (SGT)
Date of Accident	14/08/2021 07:30 (SGT)
Exact Location of Accident	BKE, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA6998G
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Company Reg No	1XXXXX821R
Email Address	fleetsafety@cdgtaxi.com.sg
Mobile Phone No	(Phone) +65-98398611
Alternative Phone No	(Office) +65-65508768

VEHICLE PARTICULARS

Manufacturer	Hyundai
Model	Ae ioniq
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1580

INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Type of Coverage	ThirdPartyFireTheft
Fleet Policy	Yes
Policy Number	VFX/P2419138
Cover Note Number	-

DRIVER

Name of Driver	TAY CHIN HIONG
NRIC No	SXXXX784Z

Date Of Birth	21/09/1965
Occupation	Outdoor
Date Of Driving Pass	13/06/1986
Driving experience	35 YEARS AND 2 MONTHS
Gender	Male
Mobile Number	(Phone) +65-98398611
Alt. Phone Number	-
Email Address	fleetsafety@cdgtaxi.com.sg
Address	BLK 747 PASIR RIS STREET 71 #06-38
Address complement	-
Postcode	510747
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collided into Motorcyclist
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	UNKNOWN
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

ON 14/08/2021 AT ABOUT 07:30HRS, I WAS DRIVING VEHICLE A (SHA6998G)) ALONG BKE TOWARDS WOODLANDS AVE 3. UPON REACHING SLIP ROAD JUNCTION, I STOP VEHICLE A AND LOOK FOR ONCOMING TRAFFIC ON MY RIGHT. WHILE VEHICLE A WAS STATIONARY, VEHICLE B COLLIDED ONTO VEHICLE A REAR BUMPER. RIDER FELL DOWN. NOBODY WAS INJURED AT THE TIME OF THE ACCIDENT.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	FILE IS NOT SUITABLE
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBH287Z
Vehicle Manufacturer	-

Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Motorcycle
Name of Driver	HONG TIONG LIN
NRIC No	SXXXX183J
Contact Number	(Phone) +65-81251322
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

ON 14/08/2021 AT ABOUT 07:30HRS, I WAS DRIVING VEHICLE A (SHA6998G)) ALONG BKE TOWARDS WOODLANDS AVE 3. UPON REACHING SLIP ROAD JUNCTION, I STOP VEHICLE A AND LOOK FOR ONCOMING TRAFFIC ON MY RIGHT. WHILE VEHICLE A WAS STATIONARY, VEHICLE B COLLIDED ONTO VEHICLE A REAR BUMPER. RIDER FELL DOWN. NOBODY WAS INJURED AT THE TIME OF THE ACCIDENT.

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

7 / 9

CLM

14/8/21 - 1120H

[Signature]
[Signature]